

EXHIBIT B1

1 Thomas A. Schultz, California SBN: 149578
2 Kyle E. Lakin, California SBN: 197928
3 LOPEZ, HODES, RESTAINO, MILMAN & SKIKOS
4 450 Newport Center Drive, 2nd Floor
5 Newport Beach, California 92660
6 (949) 640-8222 Telephone
7 (949) 640-8294 Facsimile

8 Attorneys for Plaintiff GUSTAVO COVARRUBIAS BARRIGA

ORIGINAL FILED

JUL 14 2006

**LOS ANGELES
SUPERIOR COURT**

9 SUPERIOR COURT OF THE STATE OF CALIFORNIA

10 FOR THE COUNTY OF LOS ANGELES

11 GUSTAVO COVARRUBIAS BARRIGA,) Case No.:

12)
13) PLAINTIFF,)

14) vs.)

15) GUIDANT CORPORATION; GUIDANT)
16) SALES CORPORATION; CARDIAC)
17) PACEMAKERS, INC.; BOSTON)
18) SCIENTIFIC CORPORATION;)
19) PROVIDENCE SAINT JOSEPH; and DOES)
20) 1 through 100, inclusive,)

21) DEFENDANTS.)

22) **COMPLAINT FOR DAMAGES AND**
23) **DEMAND FOR JURY TRIAL:**

- 24) 1. STRICT LIABILITY – FAILURE TO
- 25) WARN;
- 26) 2. STRICT LIABILITY – DESIGN DEFECT;
- 27) 3. STRICT LIABILITY – MANUFACTURING
- 28) DEFECT;
- 29) 4. NEGLIGENCE;
- 30) 5. BREACH OF IMPLIED WARRANTY;
- 31) 6. BREACH OF EXPRESS WARRANTY;
- 32) 7. FRAUD, DECEIT AND FRAUDULENT
- 33) CONCEALMENT;
- 34) 8. NEGLIGENT MISREPRESENTATION;
- 35) 9. INTENTIONAL INFLICTION OF
- 36) EMOTIONAL DISTRESS.

37 Plaintiff, GUSTAVO COVARRUBIAS BARRIGA, by and through his attorneys, Lopez,
38 Hodes, Restaino, Milman & Skikos, for causes of action against defendants, and each of them, alleges
39 the following:

40 **PRELIMINARY ALLEGATIONS COMMON TO ALL CAUSES OF ACTION**

41 **I. THE PARTIES AND VENUE ALLEGATIONS**

42 1. Plaintiff, GUSTAVO COVARRUBIAS BARRIGA, is a resident of the State of
43 California, County of Los Angeles. The County of Los Angeles was the County where the products

1 complained of herein were actually used. At all times herein mentioned, the County of Los Angeles
2 was the site of acts, negligence, and wrongful and tortious conduct that resulted in the injuries and
3 damages complained of as set forth herein.

4 2. Defendant PROVIDENCE SAINT JOSEPH is, and at all times herein mentioned was, a
5 corporation organized and existing under the laws of the State of California and a resident of the State
6 of California, County of Los Angeles. Plaintiff is informed and believes and thereon alleges, that at all
7 times herein concerned, PROVIDENCE SAINT JOSEPH was licensed to do business in, and was at all
8 times herein alleged doing business in the County of Los Angeles, State of California.
9

10 3. Defendant GUIDANT CORPORATION is an Indiana corporation, with its principal
11 place of business at 111 Monument Circle, 29th Floor, Indianapolis, Indiana. GUIDANT
12 CORPORATION develops technology to treat conditions such as heart disease, neurological disorders,
13 and vascular illness. Guidant's CRM Division is the division that develops, researches, advertises,
14 promotes, markets, and sells all of Guidant's ICDs and pacemakers, which are marketed under a variety
15 of trade names, with multiple models and serial numbers pertinent to each device. CRM Division's
16 operations are principally conducted out of its facilities at 4100 Hamline Avenue North, St. Paul,
17 Minnesota.

18 4. GUIDANT CORPORATION sells its ICDs and pacemakers through its wholly-owned
19 subsidiary, Defendant GUIDANT SALES. GUIDANT SALES is an Indiana corporation, with its
20 principal place of business at 111 Monument Circle in Indianapolis, Indiana.
21

22 5. Defendant CPI, a Minnesota corporation, developed Guidant's ICDs and pacemakers.
23 CPI was merged into Guidant in or about September 1994, and is now a wholly-owned subsidiary of
24 Guidant Corporation, with headquarters at 4100 Hamline Ave. North, St. Paul, Minnesota.

25 6. Defendant BOSTON SCIENTIFIC describes itself as a worldwide developer,
26 manufacturer, and marketer of medical devices, whose products are used in a broad range of
27 interventional medical specialties with reported revenue of \$6.3 billion in 2005. BOSTON
28

1 SCIENTIFIC is incorporated in the State of Delaware with its principal executive office located in
2 Natick, Massachusetts. In January 2006, BOSTON SCIENTIFIC entered into an agreement to acquire
3 GUIDANT CORPORATION and its subsidiaries for approximately \$27 billion. With final approval of
4 that merger, BOSTON SCIENTIFIC is the successor in interest to Guidant and, directly or indirectly,
5 has assumed Guidant's liabilities in this litigation. BOSTON SCIENTIFIC together with the other
6 Guidant entities referenced above, will collectively be referred to throughout this complaint as
7 GUIDANT and/or the Guidant defendants.

8
9 7. The Guidant defendants business units present themselves under the "Guidant"
10 corporate banner to the general public, including to the Food and Drug Administration ("FDA"),
11 physicians, and individuals. As the Independent Panel that reviewed Guidant Corp.'s device
12 surveillance and disclosure policies concluded, "the public views Guidant Corporation as a single
13 entity, rather than a group of individual businesses." Independent Panel Report at 16. Guidant Corp.
14 promotes such a view by, among other things, including the Guidant logo on all device marketing
15 materials.

16 8. Guidant Corp.'s business units have their own officers but are also tied together at the
17 corporate level by a structure by which Guidant Corp. oversees the business units, including through
18 the Guidant Management Committee.

19 9. The products of Guidant Corp.'s CRM Division include ICDs, pacemakers, and lead
20 systems. ICDs are implanted medical devices used to detect and treat abnormally fast and irregular
21 heart rhythms, each of which can stop or hinder the heart from pumping blood effectively throughout
22 the body and can result in sudden cardiac death. Pacemakers are medical devices used to detect and
23 treat abnormally slow heart rhythms.

24
25 10. Guidant holds itself out as "the world leader in the design and development of
26 cardiovascular medical products." Guidant Corp., Corporate Overview,
27 http://www.Guidant.com/about_us.shtml (last visited April 11, 2006). ICDs have been Guidant Corp.'s
28

1 fastest growing product for at least the last three years. The first ICD was placed on the market in 1985
2 by CPI, now wholly-owned by Guidant Corp. Between 2002 and 2004, Guidant Corp.'s revenues for
3 sales of ICDs jumped 80% to \$1.786 billion. In the past decade, implantable defibrillators and
4 pacemakers have been one of the fastest growing groups of implantable medical devices and according
5 to defendant GUIDANT CORPORATION'S Form 10-K filings, implantable defibrillators and
6 pacemakers have been one of its highest revenue generating product groups for at least the last five
7 years and is also the source of certain superlative promises, assurances and statements upon which the
8 plaintiff and the plaintiff's treating physician relied in selecting the device at issue here. Some of the
9 superlatives in GUIDANT CORPORATION'S annual reports include:
10

11 a. In its 2003 Annual Report, defendant GUIDANT CORPORATION
12 characterized itself as a "pioneer in the development of implantable Defibrillator technologies ..." and
13 that "the company's ongoing leadership is supported by remarkable capabilities in mechanical,
14 electrical and computer engineering."

15 b. Further, touting its engineering capabilities, GUIDANT CORPORATION stated
16 that "[s]uperior engineering spurred the launch of a new implantable Defibrillator in every quarter of
17 the past year." Defendant GUIDANT CORPORATION described its manufacturing facilities as
18 "exceptional."

19 c. In its 2003 Annual Report, GUIDANT CORPORATION stated "[e]xperienced
20 technicians – supported by continued investment in state-of-the-art automated manufacturing
21 equipment and expansion – have streamlined manufacturing processes to reduce costs, improve quality,
22 increase [out]-put and shorten the product development and manufacturing cycle, speeding the delivery
23 of lifesaving therapies to physicians and patients worldwide."

24 d. Emphasizing the company's focus on quality, GUIDANT CORPORATION
25 stressed in its 2003 Annual Report that it has "an unrelenting focus on quality in everything it does."
26 Defendant GUIDANT CORPORATION also publicly represented itself to be an open provider of
27
28

1 information to patients and physicians. In its 2003 Annual Report, the company stated that
2 "information for patients, physicians, and the public is available around the clock through Guidant's
3 dedicated customer and technical service representatives, as well as its comprehensive web site
4 (www.guidant.com)."

5 e. Nowhere disclosed in any of these financial reports or in its marketing pieces
6 outlined below; did the Guidant defendants reveal the truth, as laid out herein.

7
8 11. Defendant DOES 1 through 100 are individuals, corporations, partnerships or other
9 business entities licensed to do business in the State of California, having their principal place of
10 business in the State of California, and/or are residents of the State of California. Their true names or
11 capacities are unknown to Plaintiff who, therefore, sues said defendants by such fictitious names.
12 Plaintiff is informed and believes and thereon alleges that each of the fictitiously named defendants is
13 legally responsible in some manner for the events and occurrences herein alleged, and that Plaintiff's
14 injuries and damages as herein alleged were proximately caused by their conduct. Plaintiff will amend
15 this complaint to allege the true names and capacities of DOES 1 through 100 when the same have been
16 ascertained.

17 12. At all material times herein alleged, the GUIDANT defendants were engaged in the
18 business of designing, manufacturing, and assembling implantable defibrillators and pacemakers, for
19 the sale and use by members of the public, including Plaintiff, and as part of their business, defendants
20 designed, manufactured, and assembled the implantable defibrillators and/or pacemakers referenced
21 throughout this complaint and implanted into plaintiff.

22
23 13. At all times herein mentioned, the officers and/or directors of the corporate defendants
24 named herein participated in, authorized and/or directed the production and promotion of the
25 implantable defibrillators and/or pacemakers referenced herein when they knew or with the exercise of
26 reasonable care should have known, of the hazards and dangerous propensities of said product and
27
28

1 thereby actively participated in the tortious conduct which resulted in the damages and physical injuries
2 suffered by Plaintiff as described herein.

3 14. At all times herein mentioned, the defendants, and each of them, were the agents,
4 servants, employees, partners, aiders and abettors, coconspirators and/or joint venturers of some or all
5 of the other defendants herein and were at all times operating and acting within the course, scope, and
6 authority of said agency, service, employment, partnership, conspiracy, and/or joint venture, and with
7 the permission and consent of their co-defendants, and rendered substantial assistance and
8 encouragement to the other defendants, knowing that their conduct constituted a breach of duty owed to
9 Plaintiff. As such, each of said defendants is legally responsible for the actions of the other.
10

11 15. There exists and, at all times herein mentioned, there existed a unity of interest in
12 ownership between certain of the defendants and certain of the other defendants such that any
13 individuality and separateness between the certain defendants has ceased and these defendants are the
14 alter ego of the other certain defendants and exerted control over those defendants. Adherence to the
15 fiction of the separate existence of these certain defendants as an entity distinct from the other certain
16 defendants will permit an abuse of the corporate privilege and would sanction a fraud and/or would
17 promote injustice.

18 16. Plaintiff, GUSTAVO COVARRUBIAS BARRIGA had a defective Guidant ICD or
19 pacemaker surgically paced in Plaintiff's body on or about April 12, 2002. Prior to the implant,
20 Plaintiff was not advised or informed by defendants or any other person that the Guidant product
21 implanted in Plaintiff's body possessed any defect or was susceptible to malfunction and/or failure and
22 plaintiff did not learn of such potentiality until after becoming aware of the recalls and special
23 advisories from Guidant that were published from between June 17, 2005 and June 23, 2006 and which
24 are outlined in paragraph 31 below. Interestingly, these special advisories began about 3 weeks after
25 defendant GUIDANT CORPORATION'S Vice President/Chief Medical and Technology Officer sold
26 23,300 shares of stock in the company for \$1.71 million on May 17, 2005 and another 22,667 shares for
27
28

1 \$1.68 million on May 23, 2005.

2 17. On or about November 29, 2005, Plaintiff's defective implant was replaced because of
3 the Guidant Defendants' recall and the risk of malfunction and failure, which are described in more
4 detail below.

5 18. Without Plaintiff's consent, and upon information and belief, a non-medical
6 representative of the Guidant defendants, was present in the operating room during the implant and/or
7 explantation of the device, in violation of plaintiff's privacy rights.

8 **II. OVERVIEW OF CARDIAC RHYTHM MANAGEMENT IMPLANTABLE DEVICES**

9 19. Cardiovascular disease is the leading cause of death for both men and women in the
10 United States. Implantable devices for cardiac rhythm management have become an integral part of
11 cardiovascular therapy. Implantable pacemakers for individuals with bradycardia (a slow heartbeat)
12 were introduced more than 40 years ago, and the first ICD was implanted in 1980. (As used hereinafter,
13 the term "Implantable Device" will refer to pacemakers and/or ICDs manufactured and sold by
14 Defendants.) Thereafter, specialized pacemakers called cardiac resynchronization devices that improve
15 the mechanical function of the heart were introduced and combined with existing ICD technology.
16 Today, Implantable Devices are also commonly used for treatment of arrhythmia (an irregular
17 heartbeat).

18 20. There has been explosive growth in ICD use. There are now, in just the United States,
19 well over one million individuals living with an implanted cardiac rhythm device and this number is
20 increasing rapidly. In 2005, approximately 200,000 people in the United States were implanted with
21 ICDs.

22 21. The ICDs designed, manufactured and distributed into the stream of commerce by
23 Guidant consist of three components: (1) a small rectangular generator, approximately two inches wide,
24 which is implanted under the skin just below the collarbone; (2) insulated wires – or leads – which are
25

26 ///
27

1 attached to the generator and threaded through a vein to the heart, to carry the electric current from the
2 generator; and (3) two electrodes, located at the tip of each lead, which deliver an electric shock to the
3 heart.

4 22. The purpose of the ICD is to correct abnormal heart rhythm. The ICD can generate a
5 series of precisely timed, low-intensity, electrical pulses to reset the heart to normal rhythm when the
6 heart beats faster than normal (tachycardia); or the ICD can deliver sudden shocks to the heart to stop
7 potentially fatal heart quivering (ventricular fibrillation). In addition, the ICD may be programmed as a
8 pacemaker to send small electric signals if the heart beats too slowly (bradycardia).

9 23. Implantable CRT-D devices are medical devices that treat heart failure by helping the
10 lower chamber (ventricles) pump synchronously with the upper chambers (atria), while preventing the
11 heart from beating too slowly (bradycardia) and shocking or "over-drive pacing" of heartbeat rhythms
12 that are too fast (a process by which the CRT-D is paced briefly at a rhythm faster than the desired
13 rhythm in order to recapture control of the heartbeat).

14 24. All ICDs function as both pacemakers and defibrillators. The ICD can detect and correct
15 both fast and slow heart rates. The ICD corrects the slow rates and can "over-drive pace" rapid rates
16 and it also can administer shocks to treat ventricular tachycardia and ventricular fibrillation.

17 25. ICDs are used in individuals, like Plaintiffs, who have arrhythmias or irregular heartbeats
18 that are considered life-threatening. These can include individuals with ventricular fibrillation (rapid,
19 ineffective contraction of the ventricles of the heart), ventricular tachycardia (excessively rapid
20 heartbeat) that is poorly controlled by medication, or significant thickening of the heart muscle resulting
21 in arrhythmia. Such conditions can result in the loss of consciousness or death, unless the affected
22 individual receives therapy from an appropriate device to put the heart back into a normal cardiac
23 rhythm. Pacemakers are used in individuals, like Plaintiffs, who have bradycardia that is uncontrolled
24 by medicine alone.
25
26
27
28

1 26. If an implanted ICD operates properly, it can save an individual's life. If it fails to
2 operate properly, the individual could die within minutes.

3 27. Since 1958, pacemakers have been sold for implantation in individuals who have had
4 certain spontaneous and/or inducible life-threatening arrhythmias, bradycardia, heart block, and
5 congestive heart failure and those who are at high risk of developing bradycardia, heart block, or
6 arrhythmias. Pacemakers are used to manage disorders that disrupt the heart's normal electrical
7 conduction system.

8 28. Pacemakers are designed to be implanted under the skin of the chest wall. The device's
9 power source (pulse generator) is implanted in a pouch formed under the collarbone, just under the skin,
10 usually on the upper left chest. Wires, called leads, are inserted through a blood vessel and attached
11 directly into the heart. These wires, which are connected to the pacemaker or pulse generator, are
12 capable of both sensing a problematic heart rate and stimulating a more appropriate heart rate.

13 29. Some individuals are very dependent on pacemakers to maintain an adequate heart rate,
14 and therefore, cardiac output. For these individuals, failure of the cardiac pacemaker to provide pacing
15 can cause sudden faintness, or loss of consciousness, and can result in death.

16 30. At all times relevant, Guidant misrepresented the safety of its ICDs and pacemakers and
17 negligently manufactured, marketed, advertised, promoted, sold, and distributed those ICDs and
18 pacemakers as safe devices to be used for treatment of individuals with prior myocardial infarction,
19 arrhythmias, and individuals who are at high risk for developing such arrhythmias.

20 **III. IDENTIFICATION OF THE DEVICES AT ISSUE**

21 31. From between 1998 and the present, the Guidant defendants have knowingly marketed
22 defective devices without disclosing the true risks inherent in their devices, until they were forced to do
23 beginning mid 2005 to the present. A list of the notices, advisories, recalls sent from the Guidant
24 defendants, by device, model number, date of the notice of defect and the identified defect is identified
25 below:
26
27
28

Device Name	Model No.	Type	Date of Guidant/FDA Notice/Alert/Release	Problem
Pulsar	470	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Meridian	476	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery II	481	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Insignia AVT SSI	482	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia AVT SSI	482	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Entra SSI	484	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Entra SSI	484	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Entra SSI	485	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Entra SSI	485	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Pulsar	870	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Insignia AVT VDD	882	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia AVT VDD	882	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Pulsar	972	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Meridian	976	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery II	981	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Insignia AVT DDD	982	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Insignia AVT VDD	982	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Entra DDD	985	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Entra DDD	985	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Entra DDD	986	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Entra DDD	986	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Pulsar Max	1170	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Pulsar Max	1171	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Pulsar	1172	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery	1174	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery	1175	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Meridian	1176	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Pulsar Max II	1180	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Pulsar Max II	1181	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery II	1184	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery II	1186	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery II	1187	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Insignia Ultra SR	1190	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Ultra SR	1190	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia AVT SR	1192	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia AVT SR	1192	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Insignia Plus SR	1194	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Plus SR	1194	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Entra SR	1195	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Entra SR	1195	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Entra SR	1198	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Entra SR	1198	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Contak TR	1241	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Pulsar Max	1270	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Pulsar	1272	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery	1273	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery	1274	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery	1275	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Meridian	1276	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Pulsar Max II	1280	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery II	1283	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery II	1284	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery II	1285	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Discovery II	1286	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Insignia Ultra DR	1290	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Ultra DR	1290	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Insignia Ultra DR	1291	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Ultra DR	1291	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia AVT DR	1292	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia AVT DR	1292	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Entra DR	1294	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Entra DR	1294	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Entra DR	1295	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Entra DR	1295	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Entra DR	1296	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Entra DR	1296	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Plus DR	1297	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Entra DR	1297	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Insignia Plus DR	1298	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Insignia Plus DR	1298	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Entra SSI	1325	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Nexus Entra SSI	1325	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Entra SSI	1326	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Entra SSI	1326	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus AVT SSI	1328	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus AVT SSI	1328	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Intelis II	1349	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Virtus Plus II	1380	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Intelis II	1384	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Intelis II	1385	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Nexus Ultra SR	1390	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Ultra SR	1390	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus AVT SR	1392	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus AVT SR	1392	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Plus SR	1394	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Plus SR	1394	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Entra SR	1395	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Entra SR	1395	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Nexus Entra SR	1398	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Entra SR	1398	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Entra DDD	1425	Pacemaker	9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Entra DDD	1426	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Entra DDD	1426	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus AVT VDD	1428	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus AVT VDD	1428	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus AVT DDD	1432	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus AVT DDD	1432	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Entra DR	1466	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Entra DR	1466	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Plus DR	1467	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Plus DR	1467	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Plus DR	1468	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Plus DR	1468	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Virtus Plus II	1480	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Intelis II	1483	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Intelis II	1484	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Intelis II	1485	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Nexus Ultra DR	1490	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Ultra DR	1490	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Ultra DR	1491	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Ultra DR	1491	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus AVT DR	1492	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus AVT DR	1492	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Entra DR	1494	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Entra DR	1494	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Nexus Entra DR	1495	Pacemaker	(1) 9/22/2005	(1) failure mode caused by foreign material in crystal timing component; (2) another failure mode w/ root cause unknown a/o 9/22
Nexus Entra DR	1495	Pacemaker	(2) 6/23/2006	(2) issue w/ low voltage capacitor
Intelis II	1499	Pacemaker	(1) 7/18/2005, (2) 1/21/2006	degradation of hermetic sealing component
Ventak Prizm 2 VR	1860	ICD	6/26/2006	issue w/ low voltage capacitor
Ventak Prizm 2 DR	1861	ICD	(1) 5/23/05, 5/25/05, 6/17/05;	(1) wire insulator deterioration/short circuit
Ventak Prizm 2 DR	1861	ICD	(2) 6/16/05	(2) PEEK insulation material issue
Ventak Prizm 2 DR	1861	ICD	(3) 6/23/2006	issue w/ low voltage capacitor

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Vitality	1870	ICD	6/23/2006	issue w/ low voltage capacitor
Vitality	1871	ICD	6/23/2006	issue w/ low voltage capacitor
Ventak Prizm AVT	1900	ICD	6/17/2005	random memory error/latching
Vitality AVT	A135	ICD	6/17/2005	random memory error/latching
Vitality AVT	A155	ICD	(1) 6/17/2005	(1) random memory error/latching
Vitality AVT	A155	ICD	(2) 5/12/06	(2) capacitor defect (single supplier) resulting in premature battery depletion
Contak Renewal TR	H120	CRT-D	6/23/2006	issue w/ low voltage capacitor
Contak Renewal TR	H125	CRT-D	6/23/2006	issue w/ low voltage capacitor
Contak Renewal	H135	CRT-D	6/17/2005	wire insulator deterioration/short circuit
Contak Renewal TR 2	H140	CRT-D	6/23/2006	issue w/ low voltage capacitor
Contak Renewal TR 2	H145	CRT-D	6/23/2006	issue w/ low voltage capacitor
Contak Renewal 2	H155	CRT-D	6/17/2005	wire insulator deterioration/short circuit
Contak Renewal 3	H170	CRT-D	(1) 6/23/05, 8/1/05	(1) magnetic switch sticking in closed position
Contak Renewal 3	H170	CRT-D	(2) 5/10/06	(2) cracked layer of insulation in a flexible hybrid circuit
Contak Renewal 3	H170	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 3	H170	CRT-D	(4) 5/16/06	(4) capacitor defect (single supplier) resulting in premature battery depletion
Contak Renewal 3	H170	CRT-D	(5) 5/31/06	(5) battery welds performed at settings outside of typical manufacturing specifications at the supplier
Contak Renewal 3	H173	CRT-D	(1) 6/23/05, 8/1/05	(1) magnetic switch sticking in closed position
Contak Renewal 3	H173	CRT-D	(2) 5/12/06	(2) malfunction associated with subpectoral implantation with serial # facing the ribs

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Contak Renewal 3	H173	CRT-D	(3) 5/16/06	(3) capacitor defect (single supplier) resulting in premature battery depletion
Contak Renewal 3	H175	CRT-D	(1) 6/23/05, 8/1/05	(1) magnetic switch sticking in closed position
Contak Renewal 3	H175	CRT-D	(2) 5/10/06	(2) cracked layer of insulation in a flexible hybrid circuit
Contak Renewal 3	H175	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 3	H175	CRT-D	(4) 5/16/06	(4) capacitor defect (single supplier) resulting in premature battery depletion
Contak Renewal 3	H175	CRT-D	(5) 5/31/06	(5) battery welds performed at settings outside of typical manufacturing specifications at the supplier
Contak Renewal 3 HE	H177	CRT-D	(1) 6/16/05	(1) PEEK insulation material issue
Contak Renewal 3 HE	H177	CRT-D	(2) 6/23/05	(2) magnetic switch sticking in closed position
Contak Renewal 3 HE	H177	CRT-D	(3) 5/10/06	(3) cracked layer of insulation in a flexible hybrid circuit
Contak Renewal 3 HE	H177	CRT-D	(4) 5/12/06	(4) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 3 HE	H177	CRT-D	(5) 5/31/06	(5) battery welds performed at settings outside of typical manufacturing specifications at the supplier
Contak Renewal 3 HE	H179	CRT-D	(1) 6/23/05	(1) magnetic switch sticking in closed position
Contak Renewal 3 HE	H179	CRT-D	(2) 5/10/06	(2) cracked layer of insulation in a flexible hybrid circuit
Contak Renewal 3 HE	H179	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Contak Renewal 3 HE	H179	CRT-D	(4) 5/31/06	(4) battery welds performed at settings outside of typical manufacturing specifications at the supplier
Contak Renewal 4	H190	CRT-D	(1) 6/23/2005	(1) magnetic switch sticking in closed position
Contak Renewal 4	H190	CRT-D	(2) 5/10/06	(2) cracked layer of insulation in a flexible hybrid circuit
Contak Renewal 4	H190	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 4	H190	CRT-D	(4) 5/16/06	(4) capacitor defect (single supplier) resulting in premature battery depletion
Contak Renewal 4	H190	CRT-D	(5) 5/31/06	(5) battery welds performed at settings outside of typical manufacturing specifications at the supplier
Contak Renewal 4	H195	CRT-D	(1) 6/23/2005	(1) magnetic switch sticking in closed position
Contak Renewal 4	H195	CRT-D	(2) 5/10/06	(2) cracked layer of insulation in a flexible hybrid circuit
Contak Renewal 4	H195	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 4	H195	CRT-D	(4) 5/16/06	(4) capacitor defect (single supplier) resulting in premature battery depletion
Contak Renewal 4	H195	CRT-D	(5) 5/31/06	(5) battery welds performed at settings outside of typical manufacturing specifications at the supplier
Contak Renewal 4 HE	H197	CRT-D	(1) 6/23/2005	(1) magnetic switch sticking in closed position
Contak Renewal 4 HE	H197	CRT-D	(2) 5/10/06	(2) cracked layer of insulation in a flexible hybrid circuit
Contak Renewal 4 HE	H197	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 4 HE	H199	CRT-D	(1) 6/23/2005	(1) magnetic switch sticking in closed position

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Contak Renewal 4 HE	H199	CRT-D	(2) 5/12/06	(2) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 4 HE	H199	CRT-D	(3) 5/31/06	(3) battery welds performed at settings outside of typical manufacturing specifications at the supplier
Contak Renewal 3 RF	H210	CRT-D	5/24/06	Pre-implant issue: Lower than expected battery voltage prior to implant
Contak Renewal 3 RF	H215	CRT-D	5/24/06	Pre-implant issue: Lower than expected battery voltage prior to implant
Contak Renewal 3 RF HE	H217	CRT-D	5/24/06	Pre-implant issue: Lower than expected battery voltage prior to implant
Contak Renewal 3 RF HE	H219	CRT-D	5/24/06	Pre-implant issue: Lower than expected battery voltage prior to implant
Contak Renewal 4 RF	H230	CRT-D	(1) 6/23/05, 8/1/05	(1) magnetic switch sticking in closed position
Contak Renewal 4 RF	H230	CRT-D	(2) 5/24/06	(2) Pre-implant issue: Lower than expected battery voltage prior to implant
Contak Renewal 4 RF	H235	CRT-D	(1) 6/23/05, 8/1/05	(1) magnetic switch sticking in closed position
Contak Renewal 4 RF	H235	CRT-D	(2) 5/24/06	(2) Pre-implant issue: Lower than expected battery voltage prior to implant
Contak Renewal 4 RF HE	H239	CRT-D	(1) 6/23/2005	(1) magnetic switch sticking in closed position
Contak Renewal 4 RF HE	H239	CRT-D	(2) 5/24/06	(2) Pre-implant issue: Lower than expected battery voltage prior to implant
Contak Renewal 3 AVT	M150	CRT-D	(1) 6/17/05	(1) random memory error/latching
Contak Renewal 3 AVT	M150	CRT-D	(2) 6/23/05, 8/1/05	(2) magnetic switch sticking in closed position
Contak Renewal 3 AVT	M150	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 3 AVT	M155	CRT-D	(1) 6/17/05	(1) random memory error/latching
Contak Renewal 3 AVT	M155	CRT-D	(2) 6/23/05, 8/1/05	(2) magnetic switch sticking in closed position
Contak Renewal 3 AVT	M155	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 3 AVT HE	M157	CRT-D	(1) 6/7/05	(1) random memory error/latching
Contak Renewal 3 AVT HE	M157	CRT-D	(2) 6/23/05	(2) magnetic switch sticking in closed position

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Contak Renewal 3 AVT HE	M157	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 3 AVT HE	M159	CRT-D	(1) 6/7/05	(1) random memory error/latching
Contak Renewal 3 AVT HE	M159	CRT-D	(2) 6/23/05	(2) magnetic switch sticking in closed position
Contak Renewal 3 AVT HE	M159	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 4 AVT	M170	CRT-D	(1) 6/17/05	(1) random memory error/latching
Contak Renewal 4 AVT	M170	CRT-D	(2) 6/23/05, 8/1/05	(2) magnetic switch sticking in closed position
Contak Renewal 4 AVT	M170	CRT-D	(3) 5/10/06	(3) cracked layer of insulation in a flexible hybrid circuit
Contak Renewal 4 AVT	M170	CRT-D	(4) 5/12/06	(4) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 4 AVT	M170	CRT-D	(5) 5/16/06	(5) capacitor defect (single supplier) resulting in premature battery depletion
Contak Renewal 4 AVT	M175	CRT-D	(1) 6/17/05	(1) random memory error/latching
Contak Renewal 4 AVT	M175	CRT-D	(2) 6/23/05, 8/1/05	(2) magnetic switch sticking in closed position
Contak Renewal 4 AVT	M175	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 4 AVT	M175	CRT-D	(4) 5/16/06	(4) capacitor defect (single supplier) resulting in premature battery depletion
Contak Renewal 4 AVT HE	M177	CRT-D	(1) 6/17/05	(1) random memory error/latching
Contak Renewal 4 AVT HE	M177	CRT-D	(2) 6/23/05	(2) magnetic switch sticking in closed position
Contak Renewal 4 AVT HE	M177	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Contak Renewal 4 AVT HE	M179	CRT-D	(1) 6/17/05	(1) random memory error/latching
Contak Renewal 4 AVT HE	M179	CRT-D	(2) 6/23/05	(2) magnetic switch sticking in closed position
Contak Renewal 4 AVT HE	M179	CRT-D	(3) 5/12/06	(3) malfunction associated with subpectoral implantation with serial # facing the ribs
Vitality HE	T180	ICD	(1) 5/10/06	(1) cracked layer of insulation in a flexible hybrid circuit
Vitality HE	T180	ICD	(2) 5/12/06	(2) malfunction associated with subpectoral implantation with serial # facing the ribs

1	Vitality DS	T125	ICD	(1) 5/12/06	(1) capacitor defect (single supplier) resulting in premature battery depletion
2					
3	Vitality DS	T125	ICD	(2) 5/31/06	(2) battery welds performed at settings outside of typical manufacturing specifications at the supplier
4					
5	Vitality DS	T125	ICD	(3) 6/23/2006	(3) issue w/ low voltage capacitor
6	Vitality DS	T127	ICD	6/23/2006	issue w/ low voltage capacitor
7	Vitality DS VR	T135	ICD	(1) 5/12/06	(1) capacitor defect (single supplier) resulting in premature battery depletion
8					
9	Vitality DS VR	T135	ICD	(2) 6/23/2006	(2) issue w/ low voltage capacitor
10	Vitality 2 DR	T165	ICD	(1) 5/12/06	(1) capacitor defect (single supplier) resulting in premature battery depletion
11					
12	Vitality 2 DR	T165	ICD	(2) 5/31/06	(2) battery welds performed at settings outside of typical manufacturing specifications at the supplier
13					
14	Vitality 2 DR	T165	ICD	(3) 6/23/2006	(3) issue w/ low voltage capacitor
15	Vitality 2 DR	T167	ICD	6/23/2006	issue w/ low voltage capacitor
16					
17	Vitality 2 DR VR	T175	ICD	(1) 5/12/06	(1) capacitor defect (single supplier) resulting in premature battery depletion
18					
19	Vitality 2 DR VR	T175	ICD	(2) 5/31/06	(2) battery welds performed at settings outside of typical manufacturing specifications at the supplier
20					
21	Vitality 2 DR VR	T175	ICD	(3) 6/23/2006	(3) issue w/ low voltage capacitor
22	Vitality 2 DR VR	T177	ICD	6/23/2006	issue w/ low voltage capacitor

32. On May 15, 2006, Boston Scientific published an updated CRM Product Performance Report, which identified the number of known, confirmed malfunctions and premature battery depletions with respect to some of the devices referenced above. Again, not all of the devices listed above were included in this report and in the chart below, separated by device, is a list of approximately 2000 units with a known defect in the United States and over 2600 units worldwide, that have had

1 identified malfunctions and premature battery depletions with certain of Guidant ICDs and/or
 2 pacemakers:

Trade Name of Device	Model Numbers	Approval Date	US Confirmed Malfunction	US Unconfirmed Premature Battery Depletion	WW Confirmed Malfunction
CRT-D					
Contak Renewal 3 RF HE	H217 H219	Feb-05	0	0	0
Contak Renewal 3 RF	H210 H215	Feb-05	1	0	1
Contak Renewal 3 HE	H177 H179	Jun-03	21	7	21
Contak Renewal 3	H170 H175	Jun-03	40	10	40
Contak Renewal	H135	Dec-02	45	43	65
Contak Renewal TR	H120 H125	Jan-04	0	2	0
ICDs					
Vitality DR HE	T180	May-05	0	0	0
Vitality 2 EL DR	T167	Mar-04	2	0	4
Vitality 2 DR	T165	Mar-04	7	2	7
Vitality 2 EL VR	T177	Mar-04	3	0	3
Vitality 2 VR	T175	Mar-04	3	3	3
Vitality AVT A155	A155	Oct-03	36	4	36
Vitality AVT A135	A135	Mar-03	27	19	32
Vitality DS DR	T125	Jul-03	8	3	8
Vitality DS VR	T135	Jul-03	8	3	8
Vitality EL	T127	Jul-03	4	0	4
Ventak Prizm 2 DR	1861	Aug-00	148	22	188
Ventak Prizm 2 VR	1860	Aug-00	52	12	71
Ventak Prizm DR HE	1853 1858	Aug-00	74	53	106
Ventak Prizm VR HE	1852 1857	Aug-00	30	8	49
Ventak Prizm DR	1851 1856	Jan-00	259	47	382
Ventak Prizm VR	1850 1855	Jan-00	73	12	139
Pacemakers					
Insignia Ultra SR	1190	Nov-03	0	0	0
Insignia Ultra DR	1290	Nov-03	2	1	7
Insignia Ultra DR	1291	Nov-03	1	0	4
Insignia Entra SR	1195 1198	Mar-02	0	2	2
Insignia Entra DR	1296	Mar-02	3	3	5

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Insignia Entra DR	1294 1295	Mar-02	6	0	9
Insignia Plus SR	1194	Mar-02	7	1	9
Insignia Plus DR	1297	Mar-02	3	2	5
Insignia Plus DR	1298	Mar-02	33	40	40
Pulsar Max II SR	1180	May-01	1	4	2
Pulsar Max II SR	1181	May-01	0	0	1
Pulsar Max II DR	1280	May-01	12	12	1
Discovery II SR	1184	Mar-00	2	3	2
Discovery II SR	1186 1187	Mar-00	1	1	1
Discovery II DR	1283	Mar-00	16	40	19
Discovery II DR	1284 1286	Mar-00	6	5	13
Pulsar Max SR	1170	Jun-99	6	3	10
Pulsar Max SR	1171	Jun-99	5	0	8
Pulsar Max DR	1270	Jun-99	77	39	107
Pulsar DR	1272	Jun-99	1	0	2
Discovery SR	1174	Apr-98	78	8	131
Discovery SR	1175	Apr-98	1	0	3
Discovery DR	1273	Apr-98	145	67	156
Discovery DR	1274 1275	Apr-98	114	14	181
Meridian DDD	976	Apr-98	4	1	48
Meridian SSI	476	Apr-98	0	0	39
Meridian SR	1176	Apr-98	18	10	47
Meridian DR	1276	Apr-98	34	12	55
TOTALS			1417	518	2074

33. As part of the conditions of approval for the devices listed above, Defendants must ensure that no changes be made to the Device that would affect its safety or effectiveness without submission of a Pre-Market Approval ("PMA") supplement for review and approval, and that a PMA

1 supplement must be submitted when a device failure necessitates a labeling, manufacturing, or device
2 modification. Violation of such conditions voids their approval.

3 34. The removal of Devices from the market and other corrective actions taken by Guidant
4 have been classified as Class I or Class II recalls under federal regulations – the highest levels of such
5 recalls.

6 35. Under federal regulation “[r]ecall means a firm’s removal or correction of a marketed
7 product that the Food and Drug Administration considers to be in violation of the laws it administers
8 and against which the agency would initiate legal action, e.g., seizure.” 21 C.F.R. § 7.3(g) (2006).

9 36. The classification of a recall as Class I, II, or III “indicate[s] the relative degree of health
10 hazard presented by the product being recalled.” *Id.* § 7.3(m). “Class I is a situation in which there is a
11 reasonable probability that the use of, or exposure to, a violative product will cause serious adverse
12 health consequences or death.” *Id.* § 7.3(m)(1). “Class II is a situation in which use of, or exposure to,
13 a violative product may cause temporary or medically reversible adverse health consequences or where
14 the probability of serious adverse health consequences is remote.” *Id.* § 7.3(m)(2).

15 37. A device is deemed to be adulterated if, among other things, it fails to meet established
16 performance standards, or if the methods, facilities, or controls used for its manufacture, packing,
17 storage, or installation are not in conformity with federal regulations. *See* 21 U.S.C. § 351 (2006).

18 38. A device is deemed to be misbranded if, among other things, its labeling is false or
19 misleading in any particular way, or if it is dangerous to health when used in the manner prescribed,
20 recommended or suggested in the labeling thereof. *See* 21 U.S.C. § 352.

21 39. Manufacturers are required to comply with FDA regulation of medical devices, including
22 FDA regulations relating to records and reports, in order to prohibit introduction of medical devices
23 that are adulterated or misbranded, and to assure the safety and effectiveness of medical devices. In
24 particular, manufacturers must keep records and make reports if any medical device may have caused or
25 contributed to death or serious injury, or if the device has malfunctioned in a manner likely to cause or
26

1 contribute to death or serious injury. Federal law also mandates that the FDA establish regulations
2 requiring a manufacturer of a medical device to report promptly to FDA any correction or removal of a
3 device undertaken to reduce a risk to health posed by the device, or to remedy a violation of federal law
4 by which a device may present a risk to health. *See* 21 U.S.C. § 360i.

5 40. Adverse events associated with a medical device must be reported to FDA within 30
6 days after the manufacturer becomes aware that a device may have caused or contributed to death or
7 serious injury, or that a device has malfunctioned and would be likely to cause or contribute to death or
8 serious injury if the malfunction was to recur. Such reports must contain all information reasonably
9 known to the manufacturer, including any information that can be obtained by analysis, testing, or other
10 evaluation of the device, and any information in the manufacturer's possession. In addition,
11 manufacturers are responsible for conducting an investigation of each adverse event, and must evaluate
12 the cause of the adverse event. *See* 21 C.F.R. § 803.50.

14 41. Manufacturers of medical devices must also describe in every individual adverse event
15 report whether remedial action was taken in regard to the adverse event, and whether the remedial
16 action was reported to the FDA as a removal or correction of the device. *See* 21 C.F.R. § 803.52.

17 42. Manufacturers must report to the FDA in five business days after becoming aware of any
18 reportable medical device reporting ("MDR"). MDR events require the manufacturer to conduct a trend
19 analysis that necessitates remedial action to prevent an unreasonable risk of substantial harm to public
20 health. *See* 21 C.F.R. § 803.53

21 43. Device manufacturers must report promptly to the FDA any device corrections and
22 removals, and maintain records of device corrections and removals. FDA regulations require
23 submission of a written report within ten working days of any correction or removal of a device
24 initiated by the manufacturer to reduce a risk to health posed by the device, or to remedy a violation of
25 federal law caused by the device that may present a risk to health. The written submission must
26 contain, among other things, a description of the event giving rise to the information reported and the
27

1 corrective or removal actions taken, and any illness or injuries that have occurred with use of the
2 device, including reference to any device report numbers. Manufacturers must also indicate the total
3 number of devices manufactured or distributed which are subject to the correction or removal, and
4 provide a copy of all communications regarding the correction or removal. *See* 21 C.F.R. § 806.10.

5 44. Manufacturers must comply with quality system regulations that require manufacturers
6 to meet design-control requirements, including but not limited to conducting design validation to ensure
7 that devices conform to defined user needs and intended uses. Manufacturers must also meet quality
8 standards in manufacture and production. Manufacturers must establish and maintain procedures for
9 implementing corrective actions and preventive actions, and investigate the cause of nonconforming
10 product and take corrective action to prevent recurrence. Manufacturers are required to review and
11 evaluate all complaints and determine whether an investigation is necessary. Manufacturers are also
12 required to use statistical techniques where necessary to evaluate product performance. *See generally*
13 21 C.F.R. § 820.

15 45. A manufacturer must report to the FDA through a PMA supplement any new indications
16 for use of a device, labeling changes, or changes in the performance or design specifications, circuits,
17 components, ingredients, principle of operation, or physical layout of the device. A manufacturer may
18 implement changes to a device that enhance the safety of the device prior to obtaining FDA approval, if
19 the manufacturer submits a special report entitled: "Special PMA Supplement - Changes Being
20 Effected" and provides a full explanation of any labeling changes or changes in quality control or
21 manufacturing process that add a new specification of test method, or otherwise provide additional
22 assurance of purity, strength, or reliability of the device.

24 46. Federal regulations require that: "A PMA supplement must be submitted when
25 unanticipated adverse effects, increases in the incidence of anticipated adverse effects, or device failures
26 necessitate a labeling, manufacturing, or device modification." Conditions of Approval at I, attached to
27 FDA Approval Letter from Daniel G. Schultz, Deputy Director for Clinical Policy, FDA, to Kaye
28

1 Anderson, Senior U.S. Regulatory Affairs Associate, Guidant Corporation (July 18, 2002); *see* 21
2 C.F.R. § 814.39.

3 47. Guidant's failure to meet federal regulations applicable to medical devices and Guidant's
4 other acts and omissions as described herein directly and proximately caused the Devices to be in
5 violation of federal law and unfit for sale, and proximately caused harm, injury, and deaths to Plaintiffs
6 and their decedents. Plaintiffs' state law claims are based on parallel state law provisions that do not
7 conflict with federal law.

8 IV. HISTORY OF THE DEVICES

9 A. Summary

10 48. Guidant manufactured, promoted, sold, and distributed each of the Devices. At all
11 relevant times, Guidant misrepresented the safety of the Devices and negligently manufactured, sold,
12 promoted and distributed them as safe and effective Devices to be used for treatment of individuals with
13 cardiac issues.

14 49. While Guidant was aware that many of the Devices might be subject to certain random
15 and infrequent failures, Guidant was also aware of specific, potentially fatal, and nonrandom failures
16 that would occur in the Devices, but failed to disclose any of the subject risks and problems of the
17 devices and failed to take remedial steps to correct them.

18 50. In March 2005, the death Joshua Oukrop, whose Ventak Prizm 2 DR 1861 failed,
19 prompted an inquiry first by his physicians. According to a May 24, 2005, New York Times article, the
20 doctors who treated Mr. Oukrop felt that Guidant should have notified physicians of the defective
21 nature of the device, since the company "had received enough reports about the flaw to establish a
22 pattern and because high-risk individuals could suffer potentially catastrophic results," such as those
23 that befell Mr. Oukrop. Barry Meier, *Maker of Heart Device Kept Flaw From Doctors*, N.Y. Times,
24 May 24, 2006, at A. Faced with Guidant's refusal to disclose to the medical community or the public
25
26
27
28

1 the potentially fatal defects that their investigation uncovered, Mr. Oukrop's physicians brought the
2 issues to the attention of the New York Times.

3 51. The New York Times' disclosure that Guidant had known of defects in the Ventak Prizm
4 2 DR 1861 attracted a great deal of attention. As further information was revealed, it became apparent
5 that Guidant's CRM Division had known for more than three years that there were defects in the Ventak
6 Prizm 2 DR 1861 and that Guidant had been aware of defects in other Devices.

7 52. Since May 2005, Guidant has issued at least 35 notices, in the form of "Dear Doctor"
8 and "Dear Patient" letters, voluntary recalls, and medical advisories relating to the Devices. Even then,
9 some of the advisories and information provided by Guidant has been inconsistent, unclear and
10 incomplete. On at least one occasion, a Guidant suggestion was subsequently revoked by another
11 Guidant advisory. As a consequence, and as described below, today recipients and their medical
12 advisories remain confused and unclear as to the risks of the Devices and the appropriate course of
13 action to take.

14 53. Certainly, prior to 2005 and despite knowledge of defects in the Devices, Guidant failed
15 to communicate information about the defects to the medical community, individuals who had been
16 implanted with the Devices, or the public.

17 54. While Guidant had provided some information to the FDA that information was
18 incomplete and misleading and did not adequately disclose the Device defects. Guidant's flawed
19 disclosures did not comply with FDA regulations and violated the conditions of approval for the
20 Devices.
21

22 55. As a result of manufacturing defects, the Devices are unfit for the purpose for which they
23 were sold and do not function as Guidant had represented to the FDA, the medical community, and the
24 public. The Devices, in fact, may lead to serious physical trauma and/or death. Guidant knew and had
25 reason to know of this tendency for malfunction, device failures, and the resulting risk of injury and
26 death; and yet Guidant concealed, omitted, and suppressed this material information, preventing
27

1 Plaintiffs, the medical community, regulators, and the public from making informed choices about the
2 use of the Devices.

3 B. **Ventak Prizm ICDs**

4
5 56. Guidant designed, manufactured, marketed, promoted, sold, and distributed twelve
6 models of defective pacemaker/defibrillator combinations in the Ventak Prizm line of devices,
7 including the Ventak Prizm 2 VR/DR, Models 1860/1861, Ventak Prizm VR/DR, Models
8 1850/1851/1855/1856, the Ventak Prizm DR HE, Models 1852/1853, the Ventak Mini IV, Models
9 1790/1793/1796, and Ventak Mini III HE, Model 1789 (collectively, these are referred to as "Ventak
10 Prizm ICDs").

11 57. The Ventak Prizm 2 DR 1861 has a potentially fatal defect that can cause short circuiting
12 due to deterioration of a wire insulator within the lead connector block, or header, of the device. The
13 short circuit prevents the Ventak Prizm 2 DR 1861 from providing the necessary and appropriate
14 therapeutic shocks to correct a heart rhythm.

15 58. Guidant first submitted Ventak Prizm for approval in August 1996 pursuant to PMA
16 P960040. The device was originally approved for sale by Guidant on July 18, 1997. The original
17 approved device was Ventak Prizm (Models 1810 and 1815). On January 27, 1999, Guidant announced
18 the first implantation of the Ventak Prizm.

19
20 59. Pursuant to PMA Supplement P960040 S015, Guidant sought approval of Ventak Prizm
21 2 VR/DR (Models 1860 and 1861). Guidant received notice of approval of this PMA Supplement in
22 August 2000. Guidant began selling the Ventak Prizm 2 DR 1861 in 2000.

23 60. On July 18, 2002, under supplemental approval, the FDA expanded the approved
24 indication of all the Ventak Prizm ICDs for the prophylactic treatment of individuals with prior
25 myocardial infarctions and an ejection fraction of 30% or more.

26 61. According to Guidant's May 25, 2005 press release, approximately 24,000 Ventak Prizm
27 2 DR 1861 ICDs are currently implanted in individuals worldwide. *See* Press Release, Guidant Corp.,
28

1 *Guidant Notifies Physicians Regarding Ventak 1861 Prizm 2 DR Implantable Defibrillator (May 25,*
2 *2005) ("May 25 Guidant Press Release"). Guidant later informed the New York Times that as many as*
3 *37,000 defective Ventak Prizm 2 DR 1861 devices were implanted. See Barry Meier, *Flawed Implants:**
4 *Disclosure and Delay*, N.Y. Times, June 14, 2005, at C.

5 62. Guidant's Ventak Prizm 2 DR 1861s manufactured are uniformly defective in that they
6 suffer a deterioration of electrical insulation, which will eventually cause the devices to short circuit and
7 fail to function. The malfunction also erases the device's memory, such that a record of the malfunction
8 and any of the patient's previous cardiac arrhythmias is no longer stored in the device, making care
9 provisions for the individuals that much more difficult.

10 63. At present Guidant has not disclosed any test that can predict whether the device will
11 fail, and the device itself gives no warning before or during the malfunction. The defect can be readily
12 detected only in the rare event that the ICD happens to be tested by an electrophysiologist during a short
13 period of time during malfunction. It is not yet clear how often individuals will have to be examined to
14 determine whether their ICD has short circuited and it remains unclear, from what has been made
15 available to the public, as to whether there is an alternative method of identifying a defective device that
16 would minimize the need for ongoing constant examination and medical surveillance. In many cases,
17 the short circuiting erases the device's memory of any adverse event so that the usual telemetric
18 surveillance is not useful.

19 64. Explantation of the device also has risks, as the ICD is linked directly to the heart, with a
20 lead wire connection placed into the heart tissue. In this situation, scarring occurs easily.

21 65. In or before February 2002, Guidant learned that Ventak Prizm 2 DR 1861s were short
22 circuiting when attempting to build a charge to deliver a therapeutic shock. Specifically, Guidant knew
23 that electricity could arc between a lead wire and the backfill tube in the Ventak Prizm 2 DR 1861.
24
25
26
27
28

1 66. By May or June 2002, Guidant's observation of the pattern of short circuiting in the
2 Ventak Prizm 2 DR 1861 was sufficient for a Guidant Product Performance Engineer to classify the
3 problem as a "trend" that required further investigation.

4 67. Meanwhile, by April 2002, Guidant had determined that a manufacturing change should
5 be implemented to attempt to adjust the potentially fatal defect in the Ventak Prizm 2 DR 1861.
6 Without FDA approval or any contemporaneous disclosure to the FDA, the medical community, or the
7 public, Guidant modified the manufacturing specifications and process of the Ventak Prizm 2 DR 1861
8 to increase the spacing between the feedthru wire and the backfill tube through injection of additional
9 medical adhesive into the device.
10

11 68. In November 2002, once again without FDA approval or any contemporaneous
12 disclosure to the FDA, the medical community, or the public, Guidant made further modifications to the
13 manufacturing specifications and process of the Ventak Prizm 2 DR 1961 to thicken the insulation on
14 the backfill tube.

15 69. Even after April 2002, however, Guidant continued to sell the remaining defective ICDs
16 it had in its inventory stock without any disclosure regarding the potentially fatal defect. According to
17 the Independent Panel Report that investigated Guidant's practices with respect to reporting device
18 defects, Guidant allowed 4,000 such devices to be sold for implant after knowledge of the defect, 1,300
19 of which Guidant shipped after knowledge of the defects. The Independent Panel concluded that,
20 despite knowledge of the defect, Guidant made no effort to retrieve defective devices in medical
21 institutions' inventories and that subsequent manufacturing changes were not brought to the attention of
22 physicians or patients.
23

24 70. A June 2, 2005 New York Times article revealed that after April 2002, and after Guidant
25 had clear and definite knowledge of the defect, nine defective ICDs (manufactured before April 2002
26 and therefore lacking the modifications intended to increase the spacing between the feedthru wire and
27 the backfill tube) were implanted in individuals at Abbott Northwestern Hospital alone. According to a
28

1 May 24, 2005 New York Times article, in three cases, the Ventak Prizm devices failed to work when
2 doctors intentionally induced abnormal heart rhythms during checkups, forcing the doctors to rescue the
3 individuals with external defibrillator paddles of the type used in emergency rooms.

4 71. In April 2003, Guidant closed out the "trend report" on the Ventak Prizm 2 DR 1861,
5 with full knowledge that thousands of those devices that were manufactured before Guidant's changes
6 were still implanted and prone to failure.

7 72. After April 2002, Guidant received further information regarding continued failures in
8 the Ventak Prizm 2 DR 1861. For example, Guidant received reports of short circuiting in February
9 and July 2004. By February 2005, at least 25 events related to the known problem in the Ventak Prizm
10 2 DR 1861 had been reported to Guidant.

11 73. On March 14, 2005, a 21-year-old college student from Minnesota with hypertrophic
12 cardiomyopathy collapsed and died of sudden cardiac death when his Ventak Prizm 2 DR 1861 failed
13 due to an electrical short circuit.

14 74. Physicians at the Minneapolis Heart Institute Foundation explanted the failed device and
15 sent it to Guidant for analysis. Guidant's analysis confirmed that the device (i) short circuited
16 internally, (ii) had been permanently disabled and (iii) had its memory destroyed. As a result, the
17 device failed to deliver the electric shock necessary to correct the young man's heart rhythm, causing
18 his death.

19 75. Physicians at the Minneapolis Heart Institute Foundation searched the FDA database for
20 adverse events involving medical devices and identified several other reports involving the Ventak
21 Prizm 2 DR 1861, where the device short circuited and failed in the same manner as their patient's
22 device. They then confronted Guidant officials on May 12, 2005 regarding the recurring electrical
23 short-circuiting defect they had discovered in the Ventak Prizm 2 DR 1861 and reminded Guidant of its
24 obligations to notify patients and physicians of the defect. Guidant officials, however, refused and
25
26
27
28

1 maintained instead that there was no reason to notify physicians, patients, or the public of the defect in
2 their product.

3 76. Guidant made no public disclosure of the defect in the Ventak Prizm 2 DR 1861 until
4 May 23, 2005, more than three years after Guidant learned of the defect, and just hours before the New
5 York Times published an article disclosing the details of the Minnesota young man's death.

6 77. While Guidant officials took no action to warn the public of the defects in its device
7 prior to May 23, 2005, at least one Guidant official did act in the interim to sell company stock. On
8 May 17, 2005, Guidant's Chief Medical and Technology Officer sold 23,300 shares of stock in the
9 company for \$1.71 million, and on May 23, 2005, the day before the front-page article in the New York
10 Times, she sold another 22,667 shares for \$1.68 million.

11 78. On June 17, 2005, Guidant informed physicians in a Dear Doctor letter that it had
12 received twenty-eight reports of the short-circuiting failure in the Ventak Prizm 2 DR 1861s
13 manufactured prior to April of 2002, including one death related to failure of the device, and issued a
14 nationwide notification of recall of the device. See Guidant Corp., Urgent Medical Device Safety
15 Information & Corrective Action: Ventak Prizm® 2 DR, Model 1861 (June 17, 2005) ("June 17 Dear
16 Doctor Letter").

17 79. In the June 17, 2005 Dear Doctor Letter, Guidant described the malfunction as follows:
18 "[D]eterioration in a wire insulator within the lead connector block, in conjunction with other factors,
19 result[s] in an electrical short. The short caused diversion of shock therapy energy away from the heart
20 and into device circuitry. Resultant circuit damages caused permanent loss of shock therapy and
21 pacing." *Id.* at 1.

22 80. Guidant did not file the required PMA Supplement with respect to the 2002
23 manufacturing changes to the Ventak Prizm 2 DR 1861. Although Guidant filed a nonpublic annual
24 report with the FDA in August 2003, Guidant's disclosure did not reveal that the Ventak Prizm 2 DR
25 1861 ICDs might be subject to a potentially fatal failure or that Guidant's disclosure was incomplete,
26
27
28

1 misleading, and improper, and was intended to hide the known defect in existing Ventak Prizm 1861s
2 from Plaintiffs and others who were implanted with the device.

3 81. Guidant knew, as well, that the substance used to insulate the wires – polyimide – was
4 prone to failure. Guidant became aware that polyimide was specifically prone to cracking which, when
5 combined with exposure to bodily fluids, could lead to potentially fatal short circuiting in the Ventak
6 Prizm 2 DR 1861. Thus, Guidant determined that it would replace the polyimide tubing with another
7 substance, PEEK.

8 82. Finally, after public disclosures of Guidant's misconduct, on June or July of 2005,
9 Guidant applied for FDA approval to replace polyimide with PEEK in certain devices, such as the
10 Ventak Prizm 2 DR 1861. The FDA approved this change in August 2005 and, in October 2005,
11 described it as "replacing the insulating material on the feedthru wires with a different material that has
12 better degradation properties." FDA, Update of FDA Preliminary Public Health Notification*: Guidant
13 Ventak Prizm 2 DR and Contak Renewal Implantable Cardioverter Defibrillators at 1 (Oct. 13, 2005).

14 83. In Guidant's May 23, 2005, communication with doctors, it did not recommend
15 replacement of the Ventak Prizm devices. See May 25, 2005 Guidant Press Release. Moreover, reports
16 suggest that Guidant's sales representatives continued to assure physicians that it was unnecessary to
17 replace the defective devices in their individuals.

18 84. To this day, Guidant refuses to suggest replacement of the defective Ventak Prizm 2 DR
19 1861 devices. Despite patient deaths as a result of the malfunction, and despite Guidant's admission
20 that the actual rate of failures may be greater than the reported rate (because deaths associated with
21 device failures may be under-reported because the devices are not routinely evaluated post mortem),
22 Guidant told physicians to continue "normal monitoring" and did not encourage them to explant the
23 devices. More recently (and contrary to Guidant's original advice to patients and physicians), Guidant
24 has recommended that a commanded, or induced, shock may be performed to confirm the integrity of
25
26
27
28

1 circuitry for individuals implanted with a Ventak Prizm 2 DR 1861, although such testing will not
2 exclude the likelihood the device might later fail because of the defect.

3 85. Nevertheless, the FDA has classified the actions taken by Guidant with regard to the
4 Ventak Prizm 2 DR 1861 devices as Class I recalls, meaning there is "a reasonable probability" that the
5 malfunctioning device "will cause serious adverse health consequences or death." FDA News, FDA
6 Updates Consumers on Guidant Corporation's Implantable Defibrillators (July 1, 2005) ("July 1 FDA
7 Press Release"). The "recalls require Guidant to disclose the device malfunction to patients and doctors
8 while providing additional instructions for safe use of the devices." *Id.*

9
10 86. As of December 2005, the FDA reported that two deaths had been linked to the Ventak
11 Prizm 2 DR 1861. While Guidant reported a predicted occurrence rate of 0.10% to 0.24% in Ventak
12 Prizm DR 1861 devices that were manufactured on or before April 16, 2002, it stated that its
13 computations of potential occurrence rate could be artificially low and that its predictive modeling is
14 "inherently uncertain." Guidant also disclosed that a failure had been associated with a Ventak Prizm 2
15 DR 1861 that was manufactured after April 16, 2002.

16 87. At all times relevant to this action, Guidant knew, and had reason to know, that the
17 Ventak Prizm 2 DR 1861 was not safe for the individuals for whom they were prescribed and
18 implanted, because the devices malfunctioned, and therefore failed to operate in a safe and continuous
19 manner, causing serious medical problems and, in certain individuals, catastrophic injuries and deaths.

20
21 **C. Contak Renewal 1 and 2**

22 88. Guidant manufactured CRT-Ds known as Contak Renewal Model H135 and Contak
23 Renewal 2 Model H155 (hereinafter collectively "Contak Renewal 1 & 2").

24 89. In or before November 2003, Guidant became aware that the Contak Renewal 1 & 2
25 were prone to short-circuiting problems similar to those found in the Ventak Prizm 2 DR 1861. Like
26 the Ventak Prizm 2 DR 1861, the Contak Renewal 1 & 2 included polyimide tubing.

1 90. From November 2003 to May 2005, Guidant knew of multiple instances in which
2 Contak Renewal 1 & 2 devices had short circuited, including that the short circuiting had resulted in at
3 least one death.

4 91. While Guidant knew that the Contak Renewal 1 & 2 were defective, it failed to disclose
5 the defect to the FDA, the medical community, and the public and continued to sell Contak Renewal 1
6 & 2 devices with the defect. Not until September 2004 did Guidant consider stopping the sale of the
7 defective Contak Renewal 1 & 2 devices, and even then, determined that the Guidant sales staff should
8 misrepresent to the medical community the reason for any resulting inventory backorders, in order to
9 avoid questions that could lead to explanation of existing defective devices.
10

11 92. In January 2005, Guidant considered withdrawing Contak Renewal 1 & 2 devices from
12 the market because of the defects, but concluded that Guidant would not disclose the Contak Renewal 1
13 & 2 defect or withdraw the devices from the market because of the number of defective devices that
14 would be implanted by the time of any such action.

15 93. On June 17, 2005, only after Guidant had been forced to disclose the Ventak Prizm 2 DR
16 1861 defect and the FDA had initiated a review of Guidant's other Devices, did Guidant issue a letter to
17 doctors disclosing the defective nature of the Contak Renewal 1 & 2. Specifically, as to these devices,
18 Guidant stated that its laboratory analysis had proven that the Contak Renewal 1 & 2 had failed due to
19 "deterioration in a wire insulator within the lead connector block [which,] in conjunction with other
20 factors, could cause a short circuit and loss of device function due to diversion of therapy energy away
21 from the heart and into device circuitry." Guidant Corp., Urgent Medical Device Safety Information &
22 Corrective Action: Contak Renewal Model H135 and Contak Renewal 2 Model H155 Devices
23 Manufactured on or Before August 26, 2004 at 1 (June 17, 2005) ("June 17 Contak Renewal 1 & 2
24 Letter").
25

26 94. Guidant stated that there is no way of predicting whether "any particular device will
27 fail." *Id.* at 3. According to the June 17 Contak Renewal 1 & 2 Letter, fifteen reports of the
28

1 malfunction had been confirmed, at least, one of which was fatal, and approximately 16,000 of the
2 devices had been implanted worldwide. *See id.* at 1.

3 95. Since the June 17 Contak Renewal 1 & 2 Letter, more reports of the malfunction have
4 been confirmed by Guidant and at least three more deaths have been associated with the Contak
5 Renewal 1 & 2 defect.

6 96. Guidant further advised physicians to consider performing a commanded shock of the
7 ICD to confirm the integrity of the high-voltage delivery system, and warned physicians that Devices
8 that had failed should be explanted and replaced with new Devices.

9 97. Guidant also stated that, in regard to the Contak Renewal 1 & 2, it had "implemented
10 design and manufacturing corrective actions to address internal shorting within the device header. No
11 devices manufactured after August 26, 2004 have exhibited this failure." *Id.* at 3.

12 98. Once again, despite the fact that Guidant made manufacturing changes on or around
13 August 26, 2004, which it represented had corrected the defect in the Contak Renewal 1 & 2 devices,
14 Guidant failed to inform physicians, patients, and the public until the June 17 Contak Renewal 1 & 2
15 Letter.

16 99. In June 2005, Guidant recommended that physicians assess whether to replace the
17 Contak Renewal 1 & 2 devices. In September 2005, Guidant recommended that physicians reassess
18 device replacement "as a result of the increased projected rate of occurrence." Guidant Corp., Advisory
19 Update: Contak Renewal and Contak Renewal 2, Models H135 and H155 (Sept. 12, 2005).

20 100. Guidant has stated that its estimation of the level of device malfunction in the Contak
21 Renewal 1 & 2 is likely to be understated because the actual number of clinical failures may be greater
22 than the number reported and its predictive modeling is inherently uncertain.

23 101. The FDA has classified the action taken by Guidant with regard to the Contak Renewal 1
24 & 2 as a Class I recall. The recall requires Guidant to disclose the device malfunction to individuals
25 and doctors while providing additional instructions for safe use of the devices.

1 102. Meanwhile, as with the Ventak Prizm 2 DR 1861, Guidant had concluded that the
2 polyimide insulation tubing used in the Contak Renewal 1 & 2 was susceptible to cracking that could
3 result in short circuiting of the device.

4 103. As with the Ventak Prizm 2 DR 1861, each failure of a Contak Renewal 1 & 2 is
5 potentially fatal.

6 104. In December 2005, the FDA reported that there had been at least five deaths associated
7 with the defect in the Contak Renewal 1 & 2 and that additional clinical occurrences are likely.

8 105. At all times relevant to this action, Guidant knew, and had reason to know, that the
9 Contak Renewal 1 & 2 were not safe for the individuals for whom they were prescribed and implanted,
10 because the devices malfunctioned, and therefore failed to operate in a safe and continuous manner,
11 causing serious medical problems and, in certain individuals, catastrophic injuries and deaths.

12 **D. Contak Renewal 3 and 4**

13 106. Guidant also manufactured Contak Renewal 3, Contak Renewal 3 HE, Contak Renewal
14 4, Contak Renewal 4 HE, Contak Renewal 3 AVT, Contak Renewal 3 AVT HE, Contak Renewal 4
15 AVT, Contak Renewal 4 AVT HE, Renewal RF, and Renewal RF HE CRT-Ds (hereafter referred to as
16 "Contak Renewal 3 & 4").

17 107. Long before June 2005, Guidant knew that Contak Renewal 3 & 4 were subject to a
18 component failure, in which a magnetic switch can become stuck in the closed position, interfering with
19 the device's ability to treat tachyarrhythmias and depleting the battery. This failure can negatively
20 affect the functioning of the Contak Renewal 3 & 4 devices.

21 108. Guidant has recommended that physicians cease implantation of the Contak Renewal 3
22 & 4 and use a different product that contains a new switch component. As to currently implanted
23 Contak Renewal 3 & 4 devices, Guidant has recommended that individuals seek medical intervention to
24 switch the magnet off and seek immediate medical attention if the device is emitting audible tones. In
25 June 2005, Guidant promised, but has not delivered as of its latest Product Performance Report issued in
26
27
28

1 2006, a programmer software application to correct the problem. The FDA has classified Guidant's
2 actions with respect to Contak Renewal 3 & 4 as a Class II recall, which is defined as a product
3 malfunction that may cause temporary or medically reversible adverse health consequences.

4 109. At all times relevant to this action, Guidant knew, and had reason to know, that the
5 Contak Renewal 3 & 4 were not safe for the individuals for whom they were prescribed and implanted,
6 because the devices malfunctioned, and therefore failed to operate in a safe and continuous manner,
7 causing serious medical problems and potentially catastrophic injuries and deaths.

8 **E. Ventak Prizm AVT, Vitality AVT, and Renewal AVT**

9 110. Guidant manufactured potentially defective implantable atrial therapy devices called
10 Ventak Prizm AVT, Vitality AVT and Renewal AVT (collectively referred to as "AVTs"). The
11 Renewal AVT 3 and 4 devices are also subject to the same magnetic switch failure as the Contak
12 Renewal 3 & 4 devices.

13
14 111. On or before May 2002, Guidant knew that the AVTs were subject to a condition in
15 which a random memory error causes functional "latching" that limits available therapy. A "latched"
16 AVT can also enter a mode of continuous pacing at 120 beats per minute.

17 112. When an AVT is "latching," it is unable to detect and treat arrhythmias and will fail to
18 recognize and correct a cardiac rhythm that is too fast or irregular, potentially leading to injury or death.
19 Other effects of AVT "latching" include decreased cardiac output, increased myocardial oxygen
20 demand, and excessive wear on the device's battery. If the latching occurs during AVT therapy (i.e.,
21 while the AVT is attempting to deliver a shock), continuous shocks could result, regardless of whether
22 they are medically appropriate or necessary. Guidant developed and implemented a "fix" to correct the
23 latching in May 2004, but did not disclose to the FDA that the "fix" would be implemented in
24 manufacturing the AVTs until August 2005, after the exposure of the Ventak Prizm 2 DR 1861 defects.
25 Not until June 17, 2005 did Guidant notify doctors or the public that device replacement was required if
26 latching occurs and that the issue could be corrected if an implanted AVT – that had not latched – was
27 reprogrammed.
28

1 113. On or around July 22, 2005, Guidant informed doctors and the public that the
2 programming change recommended in June 2005 could actually cause latching to occur in the AVTs
3 and suggested that a “non-invasive software solution” would be available around September 2005.
4 Guidant Corp., Urgent Medical Device Safety Information & Corrective Action: Ventak Prizm AVT,
5 Vitality AVT, and Contak Renewal AVT (July 22, 2005).

6 114. In January 2006, Guidant noted that thirty more failures had been identified, several of
7 which appeared to be related to Guidant’s improper programming notification. As of April 2006,
8 Guidant has not issued the “non-invasive software solution.”

9 115. Individuals implanted with AVT devices must undergo medical monitoring to determine
10 whether their device is functioning properly. In the event Guidant issues a “software solution,”
11 individuals implanted with AVT devices will require additional medical attention to implement the
12 solution.

13 116. The FDA originally classified Guidant’s actions with regard to the AVT devices as a
14 Class II recall. However, after Guidant incorrectly advised the medical community of a programming
15 change that would actually increase the likelihood that latching would occur, the FDA converted
16 Guidant’s actions with regard to the AVT devices to a Class I recall. According to the FDA,
17 approximately 21,000 of the devices have been implanted worldwide.

18 117. At all times relevant to this action, Guidant knew, and had reason to know, that the
19 AVTs were not safe for the individuals for whom they were prescribed and implanted, because the
20 devices malfunctioned, and therefore failed to operate in a safe and continuous manner, causing serious
21 medical problems and, in certain individuals, catastrophic injuries and deaths.

22
23
24 **F. Discovery, Pulsar, Meridian, Virtus, and Intelis Pacemakers**

25 118. Guidant manufactures a family of pacemakers that includes the Pulsar Max, Pulsar,
26 Discovery, Meridian, Pulsar Max II, Discovery II, Contak TR, Virtus Plus II, and Intelis II devices
27 (hereafter referred to as “Guidant Pacemakers”). As a result of defects in manufacturing, Guidant