

**EXHIBIT B**

<b>No.</b>	<b>Element</b>	<b>Location</b>	<b>Barrier(s)</b>
5	Curb Ramp	Monona/Seminole - SE & SW	Evidence of resurfacing on Seminole. No curb ramps provided at the SE or SW corners of Seminole & Manona.
6	Curb Ramp (gutter bridge)	Monona/Lakeside - SE	V-ditch at pavement line Vertical drop off at edges No detectable warnings No grooved border
7	Curb Ramp (gutter bridge)	Monona/Lakeside - SE	V-ditch at pavement line Vertical drop off at edges No detectable warnings No grooved border
8	Curb Ramp (gutter bridge)	Monona/Lakeside - NE	Vertical drop off at edges No detectable warnings No grooved border
9	Curb Ramp (gutter bridge)	Monona/Lakeside - NW	Vertical drop off at edges No detectable warnings No grooved border +/-3/4" deep pothole on ramp Vertical break at roadway >1/2" high
12	Curb Ramp	Mohawk (mid block at Neil Cummings School) - E	Ramp slope 10% Gutter slope 25.5% Grooved border not on level surface No detectable warnings
13	Curb Ramp	Mohawk (mid block at Neil Cummings School) - W	Ramp slope 11.5% Gutter slope 19.9% Grooved border not on level surface No detectable warnings
17	Curb Ramp	Canal Pathway Hickory (near Neil Cummings School) - N	Gutter slope 11.5% 2" wide horizontal gap at gutter No detectable warnings No grooved border
19	Sidewalk	Canal Pathway at Lakeside - W	New sidewalk section 2.3-2.5% cross slope over full length
20	Curb Ramp	Canal Pathway at Lakeside - W	Vertical lip at base of ramp

**EXHIBIT B**

No.	Element	Location	Barrier(s)
21	Surfacing	Canal Pathway at Lakeside, continuing to Bike Route 16 (former railroad right-of-way)	The pathway is gravel
22	Connector	Bike route 16 at Apache	Pathway slope +/- 25% Surfacing is dirt/gravel
23	Curb Ramp	Apache/Birch	No curb ramps provided at al 4 corners
24	Curb Ramp	Lakeside/Mojave Ct.	The roadway appears to have been recently resurfaced and no curb ramps are provided
25	Curb Ramp	Lakeside/Birch	No curb ramps provided
32	Accessible Parking Space	Recreation Center Parking Lot	Access aisle 7'-9' Wide "NO PARKING" is not painted on the access aisle The ISA is worn off of the parking space surface
50	Curb Ramps	El Camino Drive (between Paradise Dr. and Paloma Estrada Ln./between El Camino and Paloma) Paloma Drive Granada Drive	The roadway appears to have been recently resurfaced and no curb ramps are provided at any of the intersections
51	Curb Ramp	Paradise Dr./El Camino - SW	Ramp slope 11% Gutter slope 10.5% No top landing provided No detectable warnings
52	Curb Ramp	Paradise Dr./El Camino - SW	Gutter slope 7.5% No detectable warnings Ped button 52" AFF Small shrouded button not operable with closed fist Tactile contrast striping not provided above ped button
53	Driveway	Paradise Dr. - South side of street West side of shopping center	Cross slope 13% No detectable warnings

**EXHIBIT B**

<b>No.</b>	<b>Element</b>	<b>Location</b>	<b>Barrier(s)</b>
54	Driveway	Paradise Dr. - South side of street West side of shopping center	Cross slope 10% No detectable warnings
55	Driveway	Paradise Dr. - South of street- Paradise Wine & Spirits	9.9% cross slope
56	Bus Stop	Paradise Drive - West side of street-5643 Paradise Dr.	No level 5'x8' pad provided
57	Curb Ramp	Paradise Dr./Marina del Presidio - EW	Case "C" ramp. South ramp section has a 10% running slope. 1/2" lip at base of ramp No detectable warnings
58	Driveway	Paradise Dr. - West side of street-5643 Paradise Dr.	Cross slope 12.8%
59	Curb Ramp	Paradise Dr./Madera del Presidio - SW	Landing slope 4.3% Landing cross slope 3.9% 1/2" lip at base of ramp Gutter slope 6.9%
60	Curb Ramp	Paradise Dr./Madera del Presidio - NW	Case "C" ramp. South ramp section has a 9.3% running slope. North ramp section has an 8.9% running slope 1/2" lip at base of ramp Gutter slope 8.5% No detectable warnings
64	Driveway	San Clemente - West side of street-Harley Davidson Dealer	Cross slope 7%
65	Driveway	San Clemente - West side of street-Harley Davidson Dealer (abandoned driveway)	Cross slope 13.2%
66	Driveway	San Clemente - West side of street-Hertz Equipment Rental	Cross slope 10.5%
67	Driveway	San Clemente - West side of street-45 Paradise Dr.	Cross slope 8.3%
68	Driveway	San Clemente - West side of street-CHP Offices (abandoned driveway)	Cross slope 14%
<b>No.</b>	<b>Element</b>	<b>Location</b>	<b>Barrier(s)</b>

