# Exhibit 1 *In camera*

Dockets.Justia.com

<u>l,</u> <u>Steve</u>



From: Kelly Haas <u>khaas@sbsb-eastham.com</u>

Sent: Saturday, September 10, 2022 6:11 PM

To: Victor Johansson Victor.Johansson@swedishclub.com; Patrik Del Mestre

Patrik.DelMestre@swedishclub.com

Cc: Tankers Swiftbulk tankers@swiftbulk.com; Swift Winchester VCG

tech.swiftwinchester@vships.no; 'Stefanos Kasselakis' <a href="mailto:sk@swiftbulk.com">sk@swiftbulk.com</a>; 'John Karystios'

jk@swiftbulk.com; Avdal, Gjermund Gjermund.Avdal@vships.no; Christoffersen, Dag

Dag.Christoffersen@vships.com; niree.mahabeer@vgrouplimited.com; Laiho, Vesa

vesa.laiho@vships.no; Nordstrand, Ronny ronny.nordstrand@vships.no; Steve Cunningham IMC

<u>scunningham@IndependentMaritime.com;</u> Robert Klawetter<u>RKlawetter@sbsb-eastham.com;</u> Dylan Hoke <u>dhoke@sbsblaw.com</u>; Kelly Haas <u>Khaas@sbsblaw.com</u>; Tate Williams <u>tate@hilderlaw.com</u>; James Bailey JBailey@sbsb-eastham.com

Subject: RE: Swift Winchester - Detained by USCG









-

Best regards,

Kelly M. Haas Partner



1001 McKinney Street | Suite 1400 Houston | Texas | 77002 (713) 893-6168 | Direct (832) 465-1176 | Cell (713) 574-2942 | Fax khaas@sbsb-eastham.com

The information transmitted, including any attachments, is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is prohibited, and all liability arising therefrom is disclaimed. If you received this in error, please contact the sender and delete the material from any computer. Thank you.

# Exhibit 2



#### Skip Navigation

#### Results for Vessel: SWIFT WINCHESTER

Service: Tank Ship

Length: 601.00 ft Breadth: 105.70 ft

Depth: 61.70 ft

Build Year: 2009 Alternate VINs: N/A

#### Vessel Information:

Vessel Name: SWIFT WINCHESTER Primary Vessel Number: 9470909 (IMO Number) Hull Identification Number: N/A Manufacturer Hull Number: N/A IMO Number: 9470909 Vessel Flag: MARSHALL ISLANDS Vessel Call Sign: V7RF3

#### Service Information:

Service Status: Active Out Of Service Date: N/A Last Removed From Service By: N/A

### **Cargo Authority:** Vessel is authorized to carry products listed on the International Certificate of Fitness and other petroleum products. **Tonnage:**

**Tonnage Information:** 

Vessel Particulars:

- 29130 Convention (Subpart B), Gross Ton
- 12052 Convention (Subpart B), Net Ton
- 56300 Displacement, Metric Ton
- 46093 Dead Weight, Metric Ton

**Vessel Documents and Certifications** 

Document	Agency	Date Issued	Expiration Date
SOLAS Cargo Ship Safety Equipment Certificate	LR	August 14,2022	April 23,2024
ISM - Safety Management Certificate	LR	August 27,2021	August 26,2026
International Oil Pollution Prevention Certificate	LR	May 13,2020	April 23,2024
ISM - Safety Management Certificate	LR	April 15,2020	May 11,2024
ISM - Safety Management Certificate	N/A	August 20,2019	May 11,2024
International Certificate of Fitness - Chemical	LR	August 11,2019	April 23,2024
International Load Line Certificate	LR	August 11,2019	April 23,2024
SOLAS Cargo Ship Safety Construction Certificate	LR	August 11,2019	April 23,2024
SOLAS Cargo Ship Safety Equipment Certificate	LR	August 11,2019	April 23,2024
Certificate of Compliance - Tank Vessel	N/A	April 18,2019	April 18,2021
International Oil Pollution Prevention Certificate	LR	April 4,2019	July 23,2019
SOLAS Cargo Ship Safety Equipment Certificate	LR	April 4,2019	July 23,2019
Certificate of Fitness - Chemical Carrier	LR	April 2,2019	July 23,2019
SOLAS Cargo Ship Safety Construction Certificate	LR	April 2,2019	July 23,2019
SOLAS Cargo Ship Safety Radio Certificate	LR	April 2,2019	July 23,2019
ISM - Document Of Compliance	LR	June 22,2018	June 30,2023
SOLAS Cargo Ship Safety Equipment Certificate	LR	June 29,2016	April 23,2019
ISM - Safety Management Certificate	LR	June 25,2014	May 11,2019
Classification Document	LR	May 12,2014	April 23,2019
International Certificate of Fitness - Chemical	LR	May 12,2014	April 23,2019
International Load Line Certificate	LR	May 12,2014	April 23,2019
International Oil Pollution Prevention Certificate	LR	May 12,2014	April 23,2019
SOLAS Cargo Ship Safety Construction Certificate	LR	May 12,2014	April 23,2019
SOLAS Cargo Ship Safety Radio Certificate	LR	May 12,2014	April 23,2019
ISM - Document Of Compliance	LR	November 5,2013	June 30,2018
Minimum Safe Manning Document	MH	February 26,2013	
Tonnage Certificate, International	LR	February 26,2013	
International Oil Pollution Prevention Certificate	N/A	May 31,2011	April 23,2014
Certificate of Compliance - Tank Vessel	N/A	May 23,2010	May 23,2012
COC-TVE Renewal	N/A	May 23,2010	May 23,2012
International Load Line Certificate	LR	April 24,2010	April 23,2014
International Certificate of Fitness - Chemical	N/A	January 19,2010	April 23,2014

ISM - Document Of Compliance	N/A	December 21,2009	September 16,2014
ISM - Safety Management Certificate	LR	December 21,2009	October 10,2014
ISM - Safety Management Certificate	LR	December 21,2009	September 16,2014
ISM - Document Of Compliance	LR	October 11,2009	October 14,2014
Classification Document	LR	April 24,2009	April 23,2014
International Oil Pollution Prevention Certificate	LR	April 24,2009	April 23,2014
Minimum Safe Manning Document	MH	April 24,2009	
SOLAS Cargo Ship Safety Construction Certificate	LR	April 24,2009	April 23,2014
SOLAS Cargo Ship Safety Equipment Certificate	LR	April 24,2009	April 23,2014
SOLAS Cargo Ship Safety Radio Certificate	LR	April 24,2009	April 23,2014
Tonnage Certificate, International	LR	April 6,2009	

Summary of Coast Guard Contacts

Click Here To View Contact Data From: 11/20/2017

**To:** 11/20/2022

(MM/DD/YYYY)

Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
7574042	Not Associated with a Case	Port Arthur, Texas	Saturday, October 8, 2022	Vessel Inspectior
	Deficiency Information			
	System	SubSystem	Cause	
	13 - Propulsion and Auxiliary Machinery	N/A - No Subsystem	Not Available	
	Description of Deficiency	-		
Resolved Pending	of a design and construction installed and protected as to being paid to moving parts, materials used in construct conditions to which it will be failure of Main Engine (ME required for Slow and Dead	other pressure vessels, assoc n adequate for the service for o reduce to a minimum any da hot surfaces and other hazarc ion, the purpose for which the e subjected and the environme o electronic governor. ME unab d slow speeds, when operating from local control station is sa	which they are intended nger to persons on boa ls. The design shall have equipment is intended, ntal conditions on boar le to maintain speed le from Bridge and Engin	d and shall be so ard, due regard ve regard to the working d. Vessel reported ss than 57rpm, e Control Room
	Due Date	Resolved	Resolved Date	,
	Monday, November 7, 2022	True	Saturday, October 8, 2	2022
	Resolution Description		- L	
	Reviewed class report atte	sting to repairs and proper fund	ction of Main Engine.	
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
7553932	1321069	Port Arthur, Texas	Wednesday, September 7, 2022	Vessel Inspection
	Deficiency Information			
	System	SubSystem	Cause	
	07 - Fire Safety	N/A - No Subsystem	Improper Installation	
	Description of Deficiency			
Resolved	be made in the structural a survey, without sanction of	o under regulations 7, 8, 9, or 1 rrangements, machinery, equip the Administration. During Por talled for the self-closing fire d 0) CH. 1 REG 11	oment and other items o t State Control exam, F	covered by the SCOs observed
	Due Date	Resolved	Resolved Date	
	Wednesday, September 7,	-	Thursday, Cantamban	
	2022	True	Thursday, September	15, 2022
		Irue	Thursday, September	15, 2022
	2022		Thursday, September	15, 2022
Developed	2022 Resolution Description		Thursday, September	15, 2022
Resolved	2022 Resolution Description Received satisfactory RO r		Cause	15, 2022
Resolved	2022 Resolution Description Received satisfactory RO r Deficiency Information	eport.		15, 2022
	2022 Resolution Description Received satisfactory RO r Deficiency Information System	eport. SubSystem N/A - No Subsystem	Cause	15, 2022
	2022 Resolution Description Received satisfactory RO r Deficiency Information System 07 - Fire Safety Description of Deficiency After any survey of the ship be made in the structural a survey, without sanction of	eport. SubSystem N/A - No Subsystem o under regulations 7, 8, 9, or 1 rrangements, machinery, equip the Administration. During Por talled for the self-closing fire d	Cause Improper Installation 0 has been completed, ment and other items of t State Control exam, F	no change shall covered by the 'SCOs observed

	Wednesday, September 7, 2022	True	Thursday, September 15, 2022	
	Resolution Description	1	I <u>I                                    </u>	
	Received satisfactory RO r	eport.		
	Deficiency Information	•		
	System	SubSystem	Cause	
	13 - Propulsion and	N/A - No Subsystem	Improper Installation	
	Auxiliary Machinery			
	Description of Deficiency			
Pending	made in the structural arrar without sanction of the Adn drain line leading to the bilg	ngements, machinery, equipme ninistration. During Port State ( ge had a fitting for which the Ch	been completed, no change shall be nt and other items covered by the survey, Control exam, PSCOs observed that a nief Engineer explained was installed to ion. 74SOLAS(20) CH. 1 REG 11	
	Due Date	Resolved	Resolved Date	
	Friday, October 7, 2022	True	Thursday, September 15, 2022	
	Resolution Description	Inde		
	Received satisfactory RO r	apart		
	Deficiency Information			
	System	SubSystem	Cause	
	13 - Propulsion and	SubSystem		
	Auxiliary Machinery	N/A - No Subsystem	Improper/Lack of Maintenance	
	Description of Deficiency	1	A 1	
Resolved	After survey of the ship und	der regulation 7, 8, 9 or 10 has	been completed, no change shall be	
Pending	made in the structural arrar	ngements, machinery, equipme	nt and other items covered by the survey,	
$\smile$			Control exam, PSCOs observed two g by electrical wire, and a spacer	
	installed where the valve sh	nould be. Engineers explained	that it was modified because the sludge	
	valve kept clogging. 74SOL	AS(20) CH. 1 REG 11		
	Due Date	Resolved	Resolved Date	
	Friday, October 7, 2022	True	Thursday, September 15, 2022	
	Resolution Description			
	Received satisfactory RO r	eport.		
	Deficiency Information			
	System	SubSystem	Cause	
	11 - Life Saving Appliances	N/A - No Subsystem	Improper/Lack of Maintenance	
	Description of Deficiency			
Resolved	working order and ready fo starboard lifeboat shaft seiz	r immediate use. During Port S	age, all life-saving appliances shall be in tate Control exam, PSCOs observed the the snap ring holding the shaft bearing SA CODE 4.4	
Ŭ	Due Date	Resolved	Resolved Date	
	Wednesday, September 7,			
	2022	True	Thursday, September 15, 2022	
	Resolution Description			
	Received satisfactory RO r	eport.		
	Deficiency Information			
	System	SubSystem	Cause	
	14 - Pollution Prevention	141 - MARPOL Annex I	Improper/Lack of Maintenance	
	Description of Deficiency	1		
Resolved	disposal otherwise of bilge recorded without delay in the that operation are complete Record Book Part 1 from 30	water which has accumulated ne Oil Record Book Part 1 so th ed. During Port State Control e:	es (sludge) and discharge overboard or in machinery spaces shall be fully nat all entries in the book appropriate to kam, PSCO's initial review of the Oil observed over 30 cubic meters of oil I REG 17.4	
	Due Date	Resolved	Resolved Date	
	Wednesday, September 7,	True	Thursday, September 15, 2022	
	2022		II	
	Resolution Description	apart		
L	Received satisfactory RO r	ероп.		
Resolved	Deficiency Information			
5	System	SubSystem	Cause	
Pending	09 - Working and Living Conditions	092 - Working Conditions	Placed in Improper Service	
	Description of Deficiency			

	be ensured. During Port St cabinet right side door oper and the left door was close	ate Control exam, PSĆOs ob n due to ambient temperature d to maintain the safety shute	e crew and ship from electrical hazards will served the ballast water treatment system e overheating the electrical components, down interlock so that the system would ck to persons on board. 74SOLAS(20) CH		
	Due Date	Resolved	Resolved Date		
		True			
	Friday, October 7, 2022		Thursday, September 15, 2022		
	Resolution Description				
	Received satisfactory RO r	eport.			
	Deficiency Information				
	System	SubSystem	Cause		
	11 - Life Saving Appliances	N/A - No Subsystem	Improper/Lack of Maintenance		
	Description of Deficiency	1			
Resolved Pending	Close automatically to prevent the entry of water when the lifeboat is waterborne. During Pol				
	Due Date	Resolved	Resolved Date		
	Wednesday, September 7, 2022	True	Thursday, September 15, 2022		
	Resolution Description				
	Received satisfactory RO r	eport.			
	Deficiency Information				
	-	CubSystem	Course		
	System	SubSystem	Cause		
	11 - Life Saving Appliances	N/A - No Subsystem	Improper/Lack of Maintenance		
~	Description of Deficiency	1			
( Resolved	Maintenance, testing, and inspections of life-saving equipment shall be carried having due regard to ensuring the reliability of such appliances. During Port Sta				
Pending	having due regard to ensur PSCOs observed oil leakin	ing the reliability of such app g out of the lifeboat engine, to	liances. During Port State Control exam,		
P	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3		
F	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra <b>Resolved</b>	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date		
P	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin <b>Due Date</b> Friday, October 7, 2022	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3		
P	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra <b>Resolved</b> True	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date		
P	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra <b>Resolved</b> True	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date		
P	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra <b>Resolved</b> True	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022		
P	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra <b>Resolved</b> True	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date		
P	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information	ing the reliability of such apping out of the lifeboat engine, to gout of the lifeboat's hull dra <b>Resolved</b> True eport.	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022		
P	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True eport. SubSystem N/A - No Subsystem	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022		
P	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ru procedures in place to main the ship in conformity with and maintenance of the pro-	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True eport. SubSystem N/A - No Subsystem folish procedures to ensure the ules and regulation. Overall contain the ship in conformity w applicable regulations. An ex- oper operation of the ship's en- communication with the comp	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022		
Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant rn procedures in place to main the ship in conformity with a and maintenance of the pro- residue management, and	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True eport. SubSystem N/A - No Subsystem folish procedures to ensure the ules and regulation. Overall contain the ship in conformity w applicable regulations. An ex- oper operation of the ship's en- communication with the comp	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 <b>Resolved Date</b> Thursday, September 15, 2022 <b>Cause</b> Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily		
Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ru procedures in place to main the ship in conformity with and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date	ing the reliability of such appig out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True eport. SubSystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem Subside regulation. Overall contain the ship in conformity wapplicable regulations. An exper operation of the ship's exper operation of the ship's exper operation of the ship's experimentication with the comparison of the ship's experimenticatin th	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. Resolved Date		
Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ru procedures in place to main the ship in conformity with and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True eport. SubSystem N/A - No Subsystem velish procedures to ensure the ules and regulation. Overall contain the ship in conformity w applicable regulations. An ex- poper operation of the ship's en- communication with the com 3 ISM CODE REG 10	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 <b>Resolved Date</b> Thursday, September 15, 2022 <b>Cause</b> Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required.		
Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ru procedures in place to main the ship in conformity with and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7,	ing the reliability of such appig out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True eport. SubSystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem Subside regulation. Overall contain the ship in conformity wapplicable regulations. An exper operation of the ship's exper operation of the ship's exper operation of the ship's experimentication with the comparison of the ship's experimenticatin th	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. Resolved Date		
Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ru procedures in place to main the ship in conformity with and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7, 2022	ing the reliability of such appig out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True Peport. SubSystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem SubSubSubser SubSubser SubSubs	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. Resolved Date		
Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant re procedures in place to main the ship in conformity with a and maintenance of the prof residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7, 2022 Resolution Description Received satisfactory RO r	ing the reliability of such appig out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True Peport. SubSystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem SubSubSubser SubSubSubser SubSubser SubSubSubser SubSubSubser SubSubser SubSubSubser SubSubser SubSubser SubSubser SubSubSubser SubSubser	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. Resolved Date		
Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ri procedures in place to main the ship in conformity with a and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7, 2022 Resolution Description Received satisfactory RO ri Deficiency Information	ing the reliability of such appig out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True Peport. SubSystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem SubSubSubsection of the ship's experimentation of the ship's experimentation with the com 3 ISM CODE REG 10 Resolved True	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 <b>Resolved Date</b> Thursday, September 15, 2022 <b>Cause</b> Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. <b>Resolved Date</b> Thursday, September 15, 2022		
Pending Resolved Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ri procedures in place to main the ship in conformity with a and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System	ing the reliability of such appig out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True Peport. SubSystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem SubSubSubser SubSubSubser SubSubser SubSubSubser SubSubSubser SubSubser SubSubSubser SubSubser SubSubser SubSubser SubSubSubser SubSubser	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. Resolved Date		
Pending Resolved Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ru procedures in place to main the ship in conformity with and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 13 - Propulsion and Auxiliary Machinery	ing the reliability of such appig out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True Peport. SubSystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem SISM CODE REG 10 Resolved True Peport. SubSystem N/A - No Subsystem	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 <b>Resolved Date</b> Thursday, September 15, 2022 <b>Cause</b> Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. <b>Resolved Date</b> Thursday, September 15, 2022		
Pending Resolved Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ri procedures in place to main the ship in conformity with a and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 13 - Propulsion and	ing the reliability of such appig out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True Peport. SubSystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem SISM CODE REG 10 Resolved True Peport. SubSystem N/A - No Subsystem	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. Resolved Date Thursday, September 15, 2022 Cause		
Pending Resolved Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ru procedures in place to main the ship in conformity with a and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 13 - Propulsion and Auxiliary Machinery Description of Deficiency The condition of the ship at the present regulations to e without danger to the ship of	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True eport. SubSystem N/A - No Subsystem // blish procedures to ensure the ules and regulation. Overall contain the ship in conformity w applicable regulations. An ex- oper operation of the ship's ex- communication with the com 3 ISM CODE REG 10 Resolved True True whether the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board.	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. Resolved Date Thursday, September 15, 2022 Cause		
Pending Resolved Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ru procedures in place to main the ship in conformity with a and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 13 - Propulsion and Auxiliary Machinery Description of Deficiency The condition of the ship at the present regulations to e without danger to the ship of	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True eport. SubSystem N/A - No Subsystem // blish procedures to ensure the ules and regulation. Overall contain the ship in conformity w applicable regulations. An ex- oper operation of the ship's ex- communication with the com 3 ISM CODE REG 10 Resolved True True whether the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board. During for the ship in all response on board.	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. Resolved Date Thursday, September 15, 2022 Cause Cause Improper/Lack of Maintenance Cause Improper/Lack of Maintenance		
Pending Resolved Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant rr procedures in place to main the ship in conformity with a and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 13 - Propulsion and Auxiliary Machinery Description of Deficiency The condition of the ship and the present regulations to evithout danger to the ship on numerous valve handles m Due Date	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True eport. SubSystem N/A - No Subsystem // lish procedures to ensure the ules and regulation. Overall c intain the ship in conformity w applicable regulations. An ex- oper operation of the ship's ec- communication with the com 3 ISM CODE REG 10 Resolved True eport. SubSystem N/A - No Subsystem // nd its equipment shall be mai ensure that the ship in all resp or persons on board. During I issing throughout the engine Resolved	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance Resolved Date Thursday, September 15, 2022 Resolved Date Resolved Date Resolved Date Resolved Date Resolved Date Resolved Date Resolved Date Resolved Date Resolved Date Resolved Date		
Pending Resolved Pending	having due regard to ensur PSCOs observed oil leakin amount that oil was drippin Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 15 - Safety Management Systems (ISM) Description of Deficiency The company should estab provisions of the relevant ri procedures in place to main the ship in conformity with a and maintenance of the pro- residue management, and 74SOLAS(20) CH. IX REG Due Date Wednesday, September 7, 2022 Resolution Description Received satisfactory RO r Deficiency Information System 13 - Propulsion and Auxiliary Machinery Description of Deficiency The condition of the ship an the present regulations to evithout danger to the ship on numerous valve handles m	ing the reliability of such app g out of the lifeboat engine, to g out of the lifeboat's hull dra Resolved True eport. SubSystem N/A - No Subsystem N/A - No Subsystem N/A - No Subsystem SubSubsystem SubSubsystem SubSubsystem SubSubsystem SubSystem N/A - No Subsystem N/A - No Subsystem	iances. During Port State Control exam, o the amount of the lifeboat engine, to the in valve. 74SOLAS(20) CH. III REG 20.3 Resolved Date Thursday, September 15, 2022 Cause Improper/Lack of Maintenance e ship is maintained in conformity with the condition of the vessel indicates that the ithin regulation are insufficient to maintain ternal ISM audit pertaining to the survey quipment to at least include piping, oily pany for maintenance needs is required. Resolved Date Thursday, September 15, 2022 Cause Cause Improper/Lack of Maintenance Cause Improper/Lack of Maintenance Cause Improper/Lack of Maintenance		

	Deficiency Information			
	System	SubSystem	Cause	
	09 - Working and Living Conditions	092 - Working Conditions	Improper/Lack of Maintenance	
	Description of Deficienc	v		
		•	ntained to conform with the provisions of	
Pending	the present regulations to without danger to the ship	ensure that the ship in all resp or persons on board. During F	Port State Control exam, PSCOs observed and did not start the fan. 74SOLAS(20)	
	Due Date	Resolved	Resolved Date	
	Friday, October 7, 2022	True	Thursday, September 15, 2022	
	Resolution Description			
	Received satisfactory RO	report.		
	Deficiency Information	•		
	System	SubSystem	Cause	
	02 - Structural Conditions	N/A - No Subsystem	Improper/Lack of Maintenance	
	Description of Deficienc			
		•		
Resolved Pending	the present regulations to without danger to the ship	ensure that the ship in all resp or persons on board. During F	ntained to conform with the provisions of ects will remain fit to proceed to sea Port State Control exam, PSCOs observe age. 74SOLAS(20) CH. 1 REG 11	
0	Due Date	Resolved	Resolved Date	
	Wednesday, September 7 2022	' True	Thursday, September 15, 2022	
	Resolution Description			
	Received satisfactory RO	report.		
	Deficiency Information			
	System	SubSystem	Cause	
	02 - Structural Conditions	N/A - No Subsystem	Improper/Lack of Maintenance	
	Description of Deficienc	у		
Resolved Pending	the present regulations to without danger to the ship	ensure that the ship in all resp or persons on board. During F	ntained to conform with the provisions of ects will remain fit to proceed to sea Port State Control exam, PSCOs observe d sea-water. 74SOLAS(20) CH. 1 REG 1	
	Due Date	Resolved	Resolved Date	
	Wednesday, September 7 2022	, True	Thursday, September 15, 2022	
	Resolution Description			
	Received satisfactory RO	report.		
	Deficiency Information			
	System	SubSystem	Cause	
	08 - Alarms	N/A - No Subsystem	Improper/Lack of Maintenance	
	Description of Deficienc			
Resolved	the present regulations to without danger to the ship that the MDO Service Tan	ensure that the ship in all resp or persons on board. During F k remove level indicator alarm	ntained to conform with the provisions of ects will remain fit to proceed to sea Port State Control exam, PSCOs observe showed that the tank was at "Low Level" cated it was not at low level. 74SOLAS(2	
	CH. 1 REG 11			
OPending	CH. 1 REG 11		Posolvod Dato	
OPending	CH. 1 REG 11 Due Date	Resolved	Resolved Date	
OPending	CH. 1 REG 11 Due Date Friday, October 7, 2022		Resolved Date Thursday, September 15, 2022	
O Pending	CH. 1 REG 11 Due Date Friday, October 7, 2022 Resolution Description	Resolved True		
OPending	CH. 1 REG 1 Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO	Resolved True		
	CH. 1 REG 11 Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Deficiency Information	Resolved	Thursday, September 15, 2022	
Pending Resolved	CH. 1 REG 11 Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Deficiency Information System	Resolved True report.	Thursday, September 15, 2022	
	CH. 1 REG 11 Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Deficiency Information System 02 - Structural Conditions	Resolved       True       report.       SubSystem       N/A - No Subsystem	Thursday, September 15, 2022	
Resolved	CH. 1 REG 11 Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Deficiency Information System	Resolved       True       report.       SubSystem       N/A - No Subsystem	Thursday, September 15, 2022	
Resolved	CH. 1 REG 11 Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Deficiency Information System 02 - Structural Conditions Description of Deficienc The condition of the ship a the present regulations to without danger to the ship	Resolved         True         report.         SubSystem         N/A - No Subsystem         y         and its equipment shall be mail         ensure that the ship in all resp         or persons on board. During F	Thursday, September 15, 2022 Cause Improper/Lack of Maintenance ntained to conform with the provisions of ects will remain fit to proceed to sea	
Resolved	CH. 1 REG 11 Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Deficiency Information System 02 - Structural Conditions Description of Deficienc The condition of the ship a the present regulations to without danger to the ship	Resolved         True         report.         SubSystem         N/A - No Subsystem         y         and its equipment shall be mail         ensure that the ship in all resp         or persons on board. During F	Thursday, September 15, 2022 Cause Improper/Lack of Maintenance tained to conform with the provisions of ects will remain fit to proceed to sea Port State Control exam, PSCOs observe	

	Received satisfactory RO r	eport.	
	Deficiency Information		
	System	SubSystem	Cause
	09 - Working and Living Conditions	091 - Living Conditions	Improper/Lack of Maintenance
	Description of Deficiency		
Resolved Pending	the present regulations to e without danger to the ship of	ensure that the ship in all respe or persons on board. During Po	tained to conform with the provisions of ects will remain fit to proceed to sea ort State Control exam, PSCOs observed clogged. 74SOLAS(20) CH. 1 REG 11
<u> </u>	Due Date	Resolved	Resolved Date
	Wednesday, September 7, 2022	True	Thursday, September 15, 2022
	Resolution Description		
	Received satisfactory RO r	eport.	
	Deficiency Information	-	
	System	SubSystem	Cause
	13 - Propulsion and Auxiliary Machinery	N/A - No Subsystem	Improper/Lack of Maintenance
	Description of Deficiency	1	
Resolved Pending	danger to the ship pr perso primary bilge pump was un effective manner, such that	ns on board. During Port State able to transfer oily residue fro	will remain fit to proceed to sea without e Control exam, PSCOs observed that the om the bilge to the bilge holding tank in a for 10 minutes and nearly no residue wa 6 11 Action Code: 30ac
	Due Date	Resolved	Resolved Date
	Wednesday, September 7, 2022	True	Friday, September 16, 2022
	L		
	Resolution Description		
			ne aft bilg well to the bilge holding tank. Received satisfactory RO report.
	Deficiency Information		
	System	SubSystem	Cause
	07 - Fire Safety	N/A - No Subsystem	Improper/Lack of Maintenance
	Description of Deficiency	r	
Resolved Pending	the present regulations to e danger to the ship pr perso	ensure the ship in all respects t ns on board. During Port State ne engine room and the crew o	tained to conform with the provisions of will remain fit to proceed to sea without control exam, PSCOs observed the sel change out room did not self close.
	Due Date	Resolved	Resolved Date
	Wednesday, September 7, 2022	True	Thursday, September 15, 2022
	Resolution Description	a t	
	Received satisfactory RO r	eport.	
	Deficiency Information		
		SubSystem	Cause
	System		
	07 - Fire Safety	N/A - No Subsystem	Improper/Lack of Maintenance
	Description of Deficiency	1	
Resolved Pending	the present regulations to e danger to the ship pr perso	ensure the ship in all respects to ns on board. During Port State ne passageway and the crew o	tained to conform with the provisions of will remain fit to proceed to sea without e Control exam, PSCOs observed the se shange out room leading to the engine
-	Due Date	Resolved	Resolved Date
	Wednesday, September 7, 2022	True	Thursday, September 15, 2022
	Resolution Description		
	Received satisfactory RO r	eport.	
-	Deficiency Information		
Resolved	System	SubSystem	Cause
	09 - Working and Living	092 - Working Conditions	Improper/Lack of Maintenance
Pending	Conditions		
O Pending	Conditions		
Pending	Description of Deficiency		novisions of this Annex and no changes

	with a wire. 74SOLAS(20)	Resolved	Resolved Date		
	Friday, October 7, 2022	True	Thursday, Septembe	r 15. 2022	
	Resolution Description	_1	,, -p		
	Received satisfactory RO	report.			
	Deficiency Information	•			
	System	SubSystem	Cause		
	01 - Certificates &	011 - Ships Certificates	Improper/Lack of Ma	intenance	
	Documentation				
	Description of Deficiency				
Resolved Pending	of the ship or efficiency or report at the earliest oppor organization respons ble for initiated to determine whet During Port State Control	rtunity to the Administration, the or issuing the relevant certificat ther a survey, as required by re	t, the master or owner of the ship sha e nominated surveyor or recognized te, who shall cause investigations to b egulations 7, 8, 9 or 10 is necessary. he vessel's RO was unaware of the		
	Due Date	Resolved	Resolved Date		
	Wednesday, September 7	, True	Thursday, Septembe	er 15, 2022	
	2022 Resolution Description			-	
	Received satisfactory RO	report			
	Deficiency Information	10pon.			
		SubSystem	Cause		
	System 09 - Working and Living				
	Conditions	092 - Working Conditions	Improper/Lack of Ma	intenance	
-	Description of Deficiency	у			
Pending	terminations and joints in a	nd supported in such a manner all conductors shall be so made control exam, PSCOs observed 0) CH. 1 REG 45.5.5	e as to retain the origin	al properties of the	
	Due Date	Resolved	Resolved Date		
	Friday, October 7, 2022	True	Thursday, Septembe	r 15, 2022	
	Resolution Description				
	Received satisfactory RO	report.			
	Deficiency Information				
	System	SubSystem	Cause		
	13 - Propulsion and Auxiliary Machinery	N/A - No Subsystem	Improper/Lack of Ma	intenance	
	Description of Deficiency	V			
Resolved	Wiring shall be installed an terminations and joints in a cable. During Port State C	nd supported in such a manner all conductors shall be so made control exam, PSCOs observed	e as to retain the origin numerous wires for th	tain the original properties of thus wires for the incinerator's ockets, sheathing missing, and	
Pending		in disrepair with wires pulled from on top of the incinerator. 74SO			
Pending					
Pending	junction boxes unsecured	on top of the incinerator. 74SO	LAS(20) CH. II-1 REG	45.5.5	
Pending	junction boxes unsecured Due Date	on top of the incinerator. 74SO	LAS(20) CH. II-1 REG	45.5.5	
Pending	junction boxes unsecured Due Date Friday, October 7, 2022	on top of the incinerator. 74SO Resolved True	LAS(20) CH. II-1 REG	45.5.5	
	junction boxes unsecured Due Date Friday, October 7, 2022 Resolution Description	on top of the incinerator. 74SO Resolved True	LAS(20) CH. II-1 REG	45.5.5	
Activity	junction boxes unsecured Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO	on top of the incinerator. 74SO Resolved True report. Responsible Unit's USCG	LAS(20) CH. II-1 REG	45.5.5	
activity lumber 376793 activity	junction boxes unsecured Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Case Number Not Associated with a	on top of the incinerator. 74SO Resolved True report. Responsible Unit's USCG Zone/Port	DLAS(20) CH. II-1 REG Resolved Date Thursday, September Incident Date Friday, January 7,	45.5.5	
activity lumber 376793 Activity lumber	junction boxes unsecured Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Case Number Not Associated with a Case	on top of the incinerator. 74SO Resolved True report. Responsible Unit's USCG Zone/Port FPO, AP, Guam Responsible Unit's USCG	DLAS(20) CH. II-1 REG Resolved Date Thursday, September Incident Date Friday, January 7, 2022	45.5.5 T 15, 2022 Activity Type Vessel Inspectio Activity Type	
Activity Jumber 376793 Activity Jumber 331139	junction boxes unsecured Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Case Number Not Associated with a Case Number Not Associated with a	on top of the incinerator. 74SO Resolved True report. Responsible Unit's USCG Zone/Port FPO, AP, Guam Responsible Unit's USCG Zone/Port	DLAS(20) CH. II-1 REG Resolved Date Thursday, September Incident Date Friday, January 7, 2022 Incident Date Thursday, October	45.5.5 or 15, 2022 Activity Type Vessel Inspection	
Activity Jumber 376793 Activity Jumber	junction boxes unsecured Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Case Number Not Associated with a Case Case Number Not Associated with a Case Deficiency Information	on top of the incinerator. 74SO          Resolved         True         report.         Responsible Unit's USCG         Zone/Port         FPO, AP, Guam         Responsible Unit's USCG         Zone/Port         San Francisco, California	DLAS(20) CH. II-1 REG Resolved Date Thursday, September Incident Date Friday, January 7, 2022 Incident Date Thursday, October	45.5.5 T 15, 2022 Activity Type Vessel Inspection Activity Type	
Activity Jumber 376793 Activity Jumber 331139	junction boxes unsecured Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Case Number Not Associated with a Case Case Number Not Associated with a Case Deficiency Information System 13 - Propulsion and	on top of the incinerator. 74SO Resolved True report. Responsible Unit's USCG Zone/Port FPO, AP, Guam Responsible Unit's USCG Zone/Port	DLAS(20) CH. II-1 REG Resolved Date Thursday, September Incident Date Friday, January 7, 2022 Incident Date Thursday, October 14, 2021	45.5.5 T 15, 2022 Activity Type Vessel Inspectio Activity Type	
Activity Jumber 376793 Activity Jumber 331139 Resolved	junction boxes unsecured Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Case Number Not Associated with a Case Case Number Not Associated with a Case Deficiency Information System 13 - Propulsion and Auxiliary Machinery	on top of the incinerator. 74SO          Resolved         True         report.         Responsible Unit's USCG         Zone/Port         FPO, AP, Guam         Responsible Unit's USCG         Zone/Port         San Francisco, California         SubSystem         N/A - No Subsystem	AAS(20) CH. II-1 REG Resolved Date Thursday, September Incident Date Friday, January 7, 2022 Incident Date Thursday, October 14, 2021 Cause	45.5.5 T 15, 2022 Activity Type Vessel Inspectio Activity Type	
Activity Jumber '376793 Activity Jumber '331139 Resolved	junction boxes unsecured Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Case Number Not Associated with a Case Case Number Not Associated with a Case Deficiency Information System 13 - Propulsion and Auxiliary Machinery Description of Deficience The machinery, boilers, ar of a design and construction	on top of the incinerator. 74SO          Resolved         True         report.         Responsible Unit's USCG         Zone/Port         FPO, AP, Guam         Responsible Unit's USCG         Zone/Port         San Francisco, California         SubSystem         N/A - No Subsystem         Y         d other pressure vessels, assoon adequate for the service for	DLAS(20) CH. II-1 REG         Resolved Date         Thursday, September         Incident Date         Friday, January 7, 2022         Incident Date         Thursday, October         14, 2021         Cause         Not Available         violated piping systems which they are intended	45.5.5 r 15, 2022 Activity Type Vessel Inspection Activity Type Vessel Inspection and fittings shall b	
Activity Jumber '376793 Activity Jumber '331139 Resolved	junction boxes unsecured Due Date Friday, October 7, 2022 Resolution Description Received satisfactory RO Case Number Not Associated with a Case Case Number Not Associated with a Case Deficiency Information System 13 - Propulsion and Auxiliary Machinery Description of Deficience The machinery, boilers, ar of a design and construction	on top of the incinerator. 74SO          Resolved         True         report.         Responsible Unit's USCG         Zone/Port         FPO, AP, Guam         Responsible Unit's USCG         Zone/Port         San Francisco, California         SubSystem         N/A - No Subsystem         y         ad other pressure vessels, association	DLAS(20) CH. II-1 REG         Resolved Date         Thursday, September         Incident Date         Friday, January 7, 2022         Incident Date         Thursday, October         14, 2021         Cause         Not Available         violated piping systems which they are intended	45.5.5 r 15, 2022 Activity Type Vessel Inspectio Activity Type Vessel Inspectio and fittings shall b	

I	Thursday, October 14,	True	Monday, October 18,	2021
	2021			2021
	Resolution Description			
A ativity	Received Class report atte			1
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6963966	Not Associated with a Case	Houston, Texas	Sunday, May 31, 2020	Vessel Inspection
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6946187	Not Associated with a Case	Houston, Texas	Thursday, April 30, 2020	Boarding
0	Operation Control Inform	nation		
	Category Type	Control Type	Initiating Port	
	Security	COTP Order (Delayed Entry/Awaiting Exam)	Sector Houston/Galve	eston
	Date Imposed	Date Removed	Reason Imposed	
	Tuesday, April 28, 2020	Thursday, April 30, 2020	Security	
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
3931900	Not Associated with a Case	San Juan, Puerto Rico	Tuesday, March 31, 2020	Vessel Inspectio
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6815686	Not Associated with a Case	BOSTON, Massachusetts	Thursday, September 19, 2019	Vessel Inspection
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
666654	1168897	STATEN ISLAND, New York	Saturday, April 20, 2019	Vessel Operational Control
0	Operation Control Inform	nation		
	Category Type	Control Type	Initiating Port	
	Safety	COTP Order (Restriction of Operations)	Sector New York	
	Date Imposed	Date Removed	Reason Imposed	
* 120-14 FI	Saturday, April 20, 2019	Saturday, April 27, 2019	Identified Hazardous/	Unsafe Condition
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
660435	1168897	WASHINGTON, District of Columbia	Tuesday, April 16, 2019	Vessel Inspectio
	Deficiency Information	20	3	
	System	SubSuctom	Cause	
		SubSystem		
	11 - Life Saving Appliances	N/A - No Subsystem	Improper/Lack of Mair	ntenance
	11 - Life Saving Appliances Description of Deficiency	N/A - No Subsystem		
Resolved	11 - Life Saving Appliances Description of Deficiency Before the ship leaves por working order and ready fo discovered, Port State Con	V/A - No Subsystem v t and at all times during the voy or immediate use. After the wire htrol Officers had the starboard	rage, all life-saving app orope failure on port life lifeboat lowered to dec	liances shall be ir boat fall was k B. Upon
	11 - Life Saving Appliances Description of Deficiency Before the ship leaves por working order and ready for discovered, Port State Cor returning the lifeboat to cra	N/A - No Subsystem y t and at all times during the voy or immediate use. After the wire throl Officers had the starboard adle position, the winch-brake m	rage, all life-saving app orope failure on port life lifeboat lowered to dec emote-release cable pa	liances shall be in boat fall was k B. Upon
	11 - Life Saving Appliances Description of Deficiency Before the ship leaves por working order and ready fo discovered, Port State Con	V/A - No Subsystem v t and at all times during the voy or immediate use. After the wire htrol Officers had the starboard	rage, all life-saving app orope failure on port life lifeboat lowered to dec	liances shall be ir boat fall was k B. Upon ırted.
	11 - Life Saving Appliances Description of Deficience Before the ship leaves por working order and ready for discovered, Port State Cor returning the lifeboat to cra Due Date	N/A - No Subsystem v t and at all times during the voy or immediate use. After the wirce htrol Officers had the starboard adle position, the winch-brake re Resolved	/age, all life-saving app prope failure on port life lifeboat lowered to dec emote-release cable pa Resolved Date	liances shall be ir boat fall was k B. Upon ırted.
	11 - Life Saving         Appliances         Description of Deficiency         Before the ship leaves por         working order and ready for         discovered, Port State Cor         returning the lifeboat to cra         Due Date         Thursday, April 18, 2019         Resolution Description	N/A - No Subsystem v t and at all times during the voy or immediate use. After the wirce htrol Officers had the starboard adle position, the winch-brake re Resolved	vage, all life-saving app e rope failure on port life lifeboat lowered to dec emote-release cable pa <b>Resolved Date</b> Saturday, April 27, 20	liances shall be ir boat fall was k B. Upon ırted. 19
	11 - Life Saving         Appliances         Description of Deficience         Before the ship leaves por         working order and ready for         discovered, Port State Cor         returning the lifeboat to crass         Due Date         Thursday, April 18, 2019         Resolution Description         Received Class Report att	N/A - No Subsystem V t and at all times during the voy or immediate use. After the wire trol Officers had the starboard adle position, the winch-brake re Resolved True	vage, all life-saving app e rope failure on port life lifeboat lowered to dec emote-release cable pa <b>Resolved Date</b> Saturday, April 27, 20	liances shall be ir boat fall was k B. Upon ırted. 19
	11 - Life Saving         Appliances         Description of Deficiency         Before the ship leaves por         working order and ready for         discovered, Port State Coor         returning the lifeboat to crass         Due Date         Thursday, April 18, 2019         Resolution Description         Received Class Report attr         remote release cable.	N/A - No Subsystem V t and at all times during the voy or immediate use. After the wire trol Officers had the starboard adle position, the winch-brake re Resolved True	vage, all life-saving app e rope failure on port life lifeboat lowered to dec emote-release cable pa <b>Resolved Date</b> Saturday, April 27, 20	liances shall be ir boat fall was k B. Upon ırted. 19
Pending	11 - Life Saving         Appliances         Description of Deficiency         Before the ship leaves por         working order and ready for         discovered, Port State Cor         returning the lifeboat to cra         Due Date         Thursday, April 18, 2019         Resolution Description         Received Class Report attr         remote release cable.         Deficiency Information	N/A - No Subsystem V t and at all times during the voy or immediate use. After the wire trol Officers had the starboard adle position, the winch-brake re Resolved True esting to new, suitably certified	vage, all life-saving app e rope failure on port life lifeboat lowered to dec emote-release cable pa <b>Resolved Date</b> Saturday, April 27, 20	liances shall be ir boat fall was k B. Upon urted. 19 winch brake
Pending	11 - Life Saving         Appliances         Description of Deficiency         Before the ship leaves por         working order and ready for         discovered, Port State Cor         returning the lifeboat to cra         Due Date         Thursday, April 18, 2019         Resolution Description         Received Class Report attremote release cable.         Deficiency Information         System         11 - Life Saving	N/A - No Subsystem         y         t and at all times during the voy         or immediate use. After the wire         https://www.commediate.com/commediate         adle position, the winch-brake model         Resolved         True         esting to new, suitably certified         SubSystem         N/A - No Subsystem	/age, all life-saving app e rope failure on port life lifeboat lowered to dec emote-release cable pa Resolved Date Saturday, April 27, 20 , wire rope on the stbd	liances shall be ir boat fall was k B. Upon urted. 19 winch brake
Pending	11 - Life Saving         Appliances         Description of Deficiency         Before the ship leaves por         working order and ready for         discovered, Port State Cor         returning the lifeboat to cra         Due Date         Thursday, April 18, 2019         Resolution Description         Received Class Report attremote release cable.         Deficiency Information         System         11 - Life Saving         Appliances         Description of Deficiency         Before the ship leaves por         working order and ready for	N/A - No Subsystem         y         t and at all times during the voy         or immediate use. After the wire         https://www.commediate.com/commediate         adle position, the winch-brake model         Resolved         True         esting to new, suitably certified         SubSystem         N/A - No Subsystem	vage, all life-saving app e rope failure on port life lifeboat lowered to dec emote-release cable pa <b>Resolved Date</b> Saturday, April 27, 20 , wire rope on the stbd v more rope on the stbd v <b>Cause</b> Improper/Lack of Main vage, all life-saving app don ship drill, port lifebo	liances shall be ir sboat fall was k B. Upon irted. 19 winch brake ntenance
Pending	11 - Life Saving         Appliances         Description of Deficiency         Before the ship leaves por         working order and ready for         discovered, Port State Cor         returning the lifeboat to cra         Due Date         Thursday, April 18, 2019         Resolution Description         Received Class Report attr         remote release cable.         Deficiency Information         System         11 - Life Saving         Appliances         Description of Deficiency         Before the ship leaves por         working order and ready for         deck B. Port State Control	N/A - No Subsystem         Y         t and at all times during the voy         or immediate use. After the wire         https://www.commediate.use.after the wire         total adde position, the winch-brake mediate         Resolved         True         esting to new, suitably certified         N/A - No Subsystem         Y         t and at all times during the voy         or immediate use. During abance	vage, all life-saving app e rope failure on port life lifeboat lowered to dec emote-release cable pa <b>Resolved Date</b> Saturday, April 27, 20 , wire rope on the stbd v more rope on the stbd v <b>Cause</b> Improper/Lack of Main vage, all life-saving app don ship drill, port lifebo	liances shall be in boat fall was k B. Upon irted. 19 winch brake ntenance liances shall be in at was lowered to
Pending	11 - Life Saving         Appliances         Description of Deficiency         Before the ship leaves por         working order and ready for         discovered, Port State Cor         returning the lifeboat to cra         Due Date         Thursday, April 18, 2019         Resolution Description         Received Class Report attremote release cable.         Deficiency Information         System         11 - Life Saving         Appliances         Description of Deficience;         Before the ship leaves por         working order and ready for         deck B. Port State Control         most fall.	N/A - No Subsystem         Y         t and at all times during the voy         or immediate use. After the wire         https://www.commediate.use         After the wire         total position, the winch-brake mediate         Resolved         True         esting to new, suitably certified         N/A - No Subsystem         Y         t and at all times during the voy or immediate use. During abance         Officers identified frayed and be	//age, all life-saving app prope failure on port life lifeboat lowered to dec emote-release cable pa <b>Resolved Date</b> Saturday, April 27, 20 , wire rope on the stbd v , wire rope on the stbd v (Cause) Improper/Lack of Main //age, all life-saving app don ship drill, port lifebo roken (16mm 19x7) wir	liances shall be in boat fall was k B. Upon urted. 19 winch brake intenance liances shall be in at was lowered to re on the forward

	Received Class Report attesting to new, suitably certified, wire ropes on the port falls.			
	Deficiency Information			
	System	SubSystem	Cause	
	15 - Safety Management Systems (ISM)	N/A - No Subsystem	Not Available	
	Description of Deficiency			
Resolved Pending	The company should identify equipment and technical systems the sudden operational failure of which may result in hazardous situations. The safety management system should provide for specific measures aimed at promoting the reliability of such equipment or systems. These measures should include the regular testing of stand-by arrangements and equipment of technical systems that are not in continuous use. Recommend recognized organization conduct external ISM audit of life-saving equipment maintenance procedures.			
	Due Date	Resolved	Resolved Date	
	Saturday, May 18, 2019	True	Sunday, May 12, 2019	
	Resolution Description			
	Received ISM Audit from Lloyd's Register. ISM was found satisfactory by Class.			
÷.	Operation Control Information			
	Category Type	Control Type	Initiating Port	
	Safety	COTP Order (Restriction of Operations)	Sector Long Island Sound	
	Date Imposed	Date Removed	Reason Imposed	
	Saturday, April 20, 2019	Sunday, April 21, 2019	Vessel Movement, Other	

Back to Top

Printer Friendly Version

Last Update: Monday, November 14, 2022

### Exhibit 3 *In camera*

From:	Kelly Haas
To:	Sam Ball
Cc:	James Bailey
Subject:	Re: Swift Winchester - update
Date:	Sunday, September 11, 2022 8:50:31 AM

X.			
			- di
	1		
	2.		
21.			

Kelly

Sent from my iPhone

On Sep 11, 2022, at 8:15 AM, Ball, Sam <sam.ball@vships.com> wrote:



Sam Ball Global Head of Assurance

Mobile +1 713 306 4042

#### Sam.ball@vships.com

As agent and manager only for and on behalf of the Owner



#### From: Ball, Sam

Sent: Sunday, September 11, 2022 8:12 AM To: 'khaas@sbsb-eastam.com' <khaas@sbsb-eastam.com>; 'damian.bratanov@lr.org' <damian.bratanov@lr.org>; tate@hilderlaw.com; MP Singh <mpsingh@3dmarine.com>; acardona@register-iri.com; Laiho, Vesa <vesa.laiho@vships.no>; 'stephanie@hinderlaw.com' <stephanie@hinderlaw.com> Cc: Nordstrand, Ronny <ronny.nordstrand@vships.no>; Avdal, Gjermund <Gjermund.Avdal@vships.no>; Bradshaw, Mike <mike.bradshaw@vships.com>; Swift Winchester <master.V7RF3@globeemail.com> Subject: Swift Winchester - update

#### Confidential - Attorney and Client Communication - Legally Privileged



Best regards,

#### Sam Ball Global Head of Assurance

Mobile +1 713 306 4042 Sam.ball@vships.com

As agent and manager only for and on behalf of the Owner



This message is intended solely for the addressee and may contain confidential information. If you have received this message in error, please send it back to us, and immediately and permanently delete it. Do not use, copy or disclose the information contained in this message or in any attachment.

### Exhibit 4 *In camera*

From:	Kelly Haas
To:	Herschaft, Jeremy A.
Cc:	Grasso, Jeanne; Linsin, Greg F.; Carlson, Kierstan
Subject:	RE: SWIFT WINCHESTER - Follow-up Regarding 3D Marine Survey Report
Date:	Tuesday, November 1, 2022 4:42:00 PM
Date:	

Kelly M. Haas D: 713.893.6168 | M: 832.465.1176



Schouest Bamdas Soshea BenMaier & Eastham

From: Herschaft, Jeremy A. <jeremy.herschaft@blankrome.com> Sent: Tuesday, November 1, 2022 3:22 PM

To: Kelly Haas <khaas@sbsblaw.com>

**Cc:** Grasso, Jeanne <jeanne.grasso@blankrome.com>; Linsin, Greg F. <greg.linsin@blankrome.com>; Carlson, Kierstan <kierstan.carlson@blankrome.com>

Subject: SWIFT WINCHESTER - Follow-up Regarding 3D Marine Survey Report



Kind regards,

#### JEREMY HERSCHAFT - BLANKROME

717 Texas Avenue, Suite 1400 | Houston, TX USA 77002 O: 713.632.8653 | C: 504.236.9726 | F: 713.228.6605 jeremy.herschaft@blankrome.com | www.blankrome.com | Bio

This message and any attachments may contain confidential or privileged information and are only for the use of the intended recipient of this message. If you are not the intended recipient, please notify the Blank Rome LLP or Blank Rome Government Relations LLC sender by return email, and delete or destroy this and all copies of this message and all attachments. Any unauthorized disclosure, use, distribution, or reproduction of this message or any attachments is prohibited and may be unlawful.

### Exhibit 5 *In camera*

From:	Kelly Haas	
To:	Stefanos Kasselakis; Patrik Del Mestre	
Cc:	James Bailey; Tankers Swiftbulk; Swift Winchester VCG; John Karystios; Avdal, Gjermund; Christoffersen, Dag; niree.mahabeer@vgrouplimited.com; Laiho, Vesa; Nordstrand, Ronny; Steve Cunningham IMC; Victor Johansson; Robert Klawetter; Dylan Hoke; Tate Williams	
Subject:	RE: Swift Winchester - Detained by USCG - TSC ref: 20222682	
Date:	Monday, September 12, 2022 10:22:00 AM	
Attachments:	image002.png image003.png image004.png	

Dear Stefanos and Patrik,

Best regards,

Kelly M. Haas D: 713.893.6168 | M: 832.465.1176



Schouest Bamdas Soshea BenMaier & Eastham

From: Stefanos Kasselakis <sk@swiftbulk.com>

Sent: Monday, September 12, 2022 10:09 AM

To: Patrik Del Mestre <Patrik.DelMestre@swedishclub.com>

Cc: Kelly Haas <Khaas@sbsblaw.com>; James Bailey <JBailey@sbsb-eastham.com>; Tankers Swiftbulk <tankers@swiftbulk.com>; Swift Winchester VCG <tech.swiftwinchester@vships.no>; John Karystios <jk@swiftbulk.com>; Avdal, Gjermund <Gjermund.Avdal@vships.no>; Christoffersen, Dag <Dag.Christoffersen@vships.com>; niree.mahabeer@vgrouplimited.com; Laiho, Vesa <vesa.laiho@vships.no>; Nordstrand, Ronny <ronny.nordstrand@vships.no>; Steve Cunningham IMC <scunningham@independentmaritime.com>; Victor Johansson <Victor.Johansson@swedishclub.com>; Robert Klawetter <RKlawetter@sbsb-eastham.com>; Dylan

Hoke <dhoke@sbsblaw.com>; Tate Williams <tate@hilderlaw.com>

Subject: Re: Swift Winchester - Detained by USCG - TSC ref: 20222682

Stefanos

On Mon, Sep 12, 2022 at 10:45 AM Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>> wrote:



To: Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>> Cc: James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>; 'Stefanos Kasselakis' <<u>sk@swiftbulk.com</u>>; 'John Karystios' <<u>jk@swiftbulk.com</u>>; Avdal, Gjermund <<u>Gjermund.Avdal@vships.no</u>>; Christoffersen, Dag <<u>Dag.Christoffersen@vships.com</u>>; niree.mahabeer@vgrouplimited.com; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>>; Steve Cunningham IMC <<u>scunningham@IndependentMaritime.com</u>>; Victor Johansson <<u>Victor.Johansson@swedishclub.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>> Subject: RE: Swift Winchester - Detained by USCG - TSC ref: 20222682

Best regards,

Kelly M. Haas D: 713.893.6168 | M: 832.465.1176



Schouest Bamdas Soshea BenMaier & Eastham

From: Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>> Sent: Monday, September 12, 2022 9:00 AM To: Kelly Haas <<u>Khaas@sbsblaw.com</u>> Cc: James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>; 'Stefanos Kasselakis' <<u>sk@swiftbulk.com</u>>; 'John Karystios' <<u>jk@swiftbulk.com</u>>; Avdal, Gjermund <<u>Gjermund.Avdal@vships.no</u>>; Christoffersen, Dag <<u>Dag.Christoffersen@vships.com</u>>; niree.mahabeer@vgrouplimited.com; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>>; Steve Cunningham IMC <<u>scunningham@IndependentMaritime.com</u>>; Victor Johansson <<u>Victor.Johansson@swedishclub.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>> Subject: RE: Swift Winchester - Detained by USCG - TSC ref: 20222682

Dear Kelly,

#### Kind Regards,

Patrik Del Mestre Claims Executive, P&I Team Sweden

The Swedish Club Tel: +46 31 638 419 Mobile: +46 730 644 663 Patrik.DelMestre@swedishclub.com www.swedishclub.com



### in 🔰

From: Kelly Haas <<u>Khaas@sbsblaw.com</u>> Sent: den 12 september 2022 15:54 To: Victor Johansson <<u>Victor.Johansson@swedishclub.com</u>>; Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>> Cc: James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>; 'Stefanos Kasselakis' <<u>sk@swiftbulk.com</u>>; 'John Karystios' <<u>jk@swiftbulk.com</u>>; Avdal, Gjermund <<u>Gjermund.Avdal@vships.no</u>>; Christoffersen, Dag <<u>Dag.Christoffersen@vships.com</u>>; niree.mahabeer@vgrouplimited.com; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>>; Steve Cunningham IMC <<u>scunningham@IndependentMaritime.com</u>>; Robert Klawetter <<u>RKlawetter@sbsbeastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>> Subject: FW: Swift Winchester - Detained by USCG - TSC ref: 20222682


Dear Gentlemen,


My colleagues advised m eis morning that they did not receive the following report, which was sent after the onboard investigation with USCG on Saturday. As such, I am resending to ensure receipt. Please confirm once received.

Kelly M. Haas D: 713.893.6168 | M: 832.465.1176 From: Kelly Haas <u>khaas@sbsb-eastham.com</u> Sent: Saturday, September 10, 2022 6:11 PM To: Victor Johansson <u>Victor.Johansson@swedishclub.com</u>; Patrik Del Mestre <u>Patrik.DelMestre@swedishclub.com</u> Cc: Tankers Swiftbulk <u>tankers@swiftbulk.com</u>; Swift Winchester VCG tech.swiftwinchester@vships.no; 'Stefanos Kasselakis' <u>sk@swiftbulk.com</u>; 'John Karystios' <u>jk@swiftbulk.com</u>; Avdal, Gjermund <u>Gjermund.Avdal@vships.no</u>; Christoffersen, Dag Dag.Christoffersen@vships.com; niree.mahabeer@vgrouplimited.com; Laiho, Vesa vesa.laiho@vships.no; Nordstrand, Ronny <u>ronny.nordstrand@vships.no</u>; Steve Cunningham IMC scunningham@IndependentMaritime.com; Robert Klawetter <u>RKlawetter@sbsb-eastham.com</u>; Dylan Hoke <u>dhoke@sbsblaw.com</u>; Kelly Haas <u>Khaas@sbsblaw.com</u>; Tate Williams tate@hilderlaw.com; James Bailey <u>JBailey@sbsb-eastham.com</u> Subject: RE: Swift Winchester - Detained by USCG

Victor and Patrik,

In addition to the undersigned, the following were onboard the M/T SWIFT WINCHESTER for the investigation today:







Best regards,

Kelly M. Haas Partner



1001 McKinney Street | Suite 1400 Houston | Texas | 77002 (713) 893-6168 | Direct (832) 465-1176 | Cell (713) 574-2942 | Fax khaas@sbsb-eastham.com

The information transmitted, including any attachments, is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is prohibited, and all liability arising therefrom is disclaimed. If you received this in error, please contact the sender and delete the material from any computer. Thank you.

The Swedish Club processes personal data in accordance with a privacy policy which can be found  $\underline{here}$ 

CONFIDENTIAL: This e-mail message and any attachments are private communication and may contain confidential, or otherwise legally privileged information meant solely for the intended recipient. If you are not the intended recipient, you are hereby notified that any use, dissemination, distribution or copying of this communication is strictly prohibited. Please notify the sender immediately by replying to this message, then delete the e-mail and any attachments from your system. Thank you.

The Swedish Club processes personal data in accordance with a privacy policy which can be found here

CONFIDENTIAL. This e-mail message and any attachments are private communication and may contain confidential, or otherwise legally privileged information meant solely for the intended recipient. If you are not the intended recipient, you are hereby notified that any use, dissemination, distribution or copying of this communication is strictly prohibited. Please notify the sender immediately by replying to this message, then delete the e-mail and any attachments from your system . Thank you.

ι.

### Exhibit 6 *In camera*

.

From:	Kelly Haas
To:	Stefanos Kasselakis
Cc:	Patrik Del Mestre; James Bailey; Tankers Swiftbulk; Swift Winchester VCG; John Karystios; Avdal, Gjermund; Christoffersen, Dag; nirce.mahabeer@worouplimited.com; Laiho. Vesa; Nordstrand, Ronny; Steve Cunningham JMC; Victor Johansson; Robert Klawetter; Dylan Hoke; Tate Williams; Stephanie K. McGuire (stephanie@hilderlaw.com); Grasso. Jeanne; jeremy.herschaft@blankrome.com; kierstan.carlson@blankrome.com; greg.linsin@blankrome.com; Rifkind. Neil; Kwok. Siew
Subject:	Re: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682
Date:	Tuesday, September 13, 2022 8:37:17 AM

Dear Stefanos,

I know Jeremy well and will coordinate with and assist him as instructed.

Kelly

Sent from my iPhone

On Sep 13, 2022, at 8:27 AM, Stefanos Kasselakis <sk@swiftbulk.com> wrote:

Kelly & all,

Please note Owners have engaged new counsel, Blank Rome, in copy.

Owners ask and fully expect the utmost cooperation with the Blank Rome team by all parties involved.

Thanks in advance.

On Mon, Sep 12, 2022 at 9:43 PM Kelly Haas <<u>Khaas@sbsblaw.com</u>> wrote:



Best regards,

Kelly M. Haas

Partner



1001 McKinney Street | Suite 1400

Houston | Texas | 77002


(713) 893-6168 | Direct


(832) 465-1176 | Cell

(713) 574-2942 | Fax

khaas@sbsb-eastham.com

The information transmitted, including any attachments, is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is prohibited, and all liability arising therefrom is disclaimed. If you received this in error, please contact the sender and delete the material from any computer. Thank you.





## Exhibit 7 *In camera*

From:	Nordstrand, Ronny	
To:	"ik"; Laiho, Vesa; Swift Winchester VCG	
Cc:	James Bailey; Tankers Swiftbulk; Mahabeer, Niree; Steve Cunningham IMC; Victor Johansson; Robert Klawetter; Dylan Hoke; Tate Williams; Stephanie K. McGuire (stephanie@hilderlaw.com); Patrik Del Mestre; Kelly Haas; Stefanos Kasselakis; Christoffersen, Dag; Avdal, Gjermund	
Subject:	RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682	
Date:	Tuesday, September 13, 2022 3:45:19 AM	
Attachments:	Swift Winchester 22 6822 H Bkwint General Service Report.pdf	

John

Best Regards **Ronny Nordstrand** Senior Fleet Manager – V. Ships Norway As agent and manager only for and on behalf of the Owner

Tel: +47 23 25 10 00 Direct: +47 23 25 10 21 Mob: +47 917 79 206 Email: ronny.nordstrand@vships.no



From: jk <jk@swiftbulk.com>

Sent: 13 September 2022 04:53

To: Nordstrand, Ronny <ronny.nordstrand@vships.no>; Laiho, Vesa <vesa.laiho@vships.no>; Swift Winchester VCG <tech.swiftwinchester@vships.no>

**Cc:** James Bailey <JBailey@sbsb-eastham.com>; Tankers Swiftbulk <tankers@swiftbulk.com>; Mahabeer, Niree <niree.mahabeer@vgrouplimited.com>; Nordstrand, Ronny

<ronny.nordstrand@vships.no>; Steve Cunningham IMC

<scunningham@independentmaritime.com>; Victor Johansson

<Victor.Johansson@swedishclub.com>; Robert Klawetter <RKlawetter@sbsb-eastham.com>; Dylan Hoke <dhoke@sbsblaw.com>; Tate Williams <tate@hilderlaw.com>; Stephanie K. McGuire

(stephanie@hilderlaw.com) <stephanie@hilderlaw.com>; Patrik Del Mestre

<Patrik.DelMestre@swedishclub.com>; Kelly Haas <Khaas@sbsblaw.com>; Stefanos Kasselakis <sk@swiftbulk.com>; Christoffersen, Dag <Dag.Christoffersen@vships.com>; Avdal, Gjermund <Gjermund.Avdal@vships.no>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

J. Karystios SwiftBulk | SwiftTankers jk@swiftbulk.com ----- Original message ------

From: Kelly Haas <<u>Khaas@sbsblaw.com</u>>

Date: 9/13/22 04:43 (GMT+02:00)

To: Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>, Patrik Del Mestre

<Patrik.DelMestre@swedishclub.com>

Cc: James Bailey <<u>JBailey@sbsb-eastham.com</u>>, Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>, Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>, John Karystios <<u>jk@swiftbulk.com</u>>, "Avdal, Gjermund" <<u>Gjermund.Avdal@vships.no</u>>, "Christoffersen, Dag" <<u>Dag.Christoffersen@vships.com</u>>, <u>niree.mahabeer@vgrouplimited.com</u>, "Laiho, Vesa" <<u>vesa.laiho@vships.no</u>>, "Nordstrand, Ronny" <<u>ronny.nordstrand@vships.no</u>>, Steve Cunningham IMC

<<u>scunningham@independentmaritime.com</u>>, Victor Johansson

<<u>Victor.Johansson@swedishclub.com</u>>, Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>, Dylan Hoke <<u>dhoke@sbsblaw.com</u>>, Tate Williams <<u>tate@hilderlaw.com</u>>, "Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>)" <<u>stephanie@hilderlaw.com</u>>

Subject: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Dear Stefanos and Patrik,

Please accept the following status report regarding the information received today.

Best regards,

Kelly M. Haas Partner



Bamdas Soshea BenMaier & Eastham


1001 McKinney Street | Suite 1400 Houston | Texas | 77002 (713) 893-6168 | Direct (832) 465-1176 | Cell (713) 574-2942 | Fax khaas@sbsb-eastham.com

The information transmitted, including any attachments, is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is prohibited, and all liability arising therefrom is disclaimed. If you received this in error, please contact the sender and delete the material from any computer. Thank you.

This message is intended solely for the addressee and may contain confidential information. If you have received this message in error, please send it back to us, and immediately and permanently delete it. Do not use, copy or disclose the information contained in this message or in any attachment.

### 7A514704-8C43-44DC-8808-95528741019F

1



7A514704-8C43-44DC-880B-95528741019F

## Exhibit 8 *In camera*

From:	Grasso, Jeanne
To:	Stefanos Kasselakis; Kelly Haas
Cc:	Avdal, Giermund; Carlson, Kierstan; Christoffersen, Dan; Herschaft, Jeremy A.; James Bailey; Kwok, Siew; Laiho, Vesa; Linsin, Gren F.; Mahabeer, Niree; Nordstrand, Bonny; Patrik Del Mestre; Rifkind, Neij: Nobert Klawetter; Stephanie K. McGuire (stephanie@hilderlaw.com); Steve Cunningham IMC; Swift Winchester VCG; Tankers Swiftbulk; Tate Williams; Victor Johansson; ik
Subject:	RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682
Date:	Tuesday, September 13, 2022 3:54:13 PM
Attachments:	

#### Jeanne M. Grasso | BLANKROME

1825 Eye Street NW | Washington, DC 20006-5403 Tel: +1 202.772.5927 | Mob: +1 202.431.2240 | Email: jeanne.grasso@blankrome.com

Winner of Lloyd's List 2019 Maritime Legal Services Award

BLANK ROME COVID-19 Task Force Page

From: Stefanos Kasselakis <sk@swiftbulk.com>

Sent: Tuesday, September 13, 2022 4:49 PM

To: Kelly Haas <Khaas@sbsblaw.com>

Cc: Avdal, Gjermund <Gjermund.Avdal@vships.no>; Carlson, Kierstan <kierstan.carlson@blankrome.com>; Christoffersen, Dag <Dag.Christoffersen@vships.com>; Grasso, Jeanne <jeanne.grasso@blankrome.com>; Herschaft, Jeremy A.


<jeremy.herschaft@blankrome.com>; James Bailey <JBailey@sbsb-eastham.com>; Kwok, Siew <SKwok@tiptreeinc.com>; Laiho, Vesa <vesa.laiho@vships.no>; Linsin, Greg F. <greg.linsin@blankrome.com>; Mahabeer, Niree <niree.mahabeer@vgrouplimited.com>; Nordstrand, Ronny <ronny.nordstrand@vships.no>; Patrik Del Mestre <Patrik.DelMestre@swedishclub.com>; Rifkind, Neil <NRifkind@tiptreeinc.com>; Robert Klawetter <RKlawetter@sbsb-eastham.com>; Stephanie K. McGuire (stephanie@hilderlaw.com) <stephanie@hilderlaw.com>; Steve Cunningham IMC <scunningham@independentmaritime.com>; Swift Winchester VCG <tech.swiftwinchester@vships.no>; Tankers Swiftbulk <tankers@swiftbulk.com>; Tate Williams <tate@hilderlaw.com>; Victor Johansson <Victor Johansson@swedishclub.com>; jk <jk@swiftbulk.com>

Subject: Re: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Thanks for the update, Kelly.

Copying the Blank Rome and in house team here as well.

On Tue, Sep 13, 2022 at 16:44 Kelly Haas <<u>Khaas@sbsblaw.com</u>> wrote:



Best regards,

Kelly M. Haas D: 713.893.6168 | M: 832.465.1176



# Schouest Bamdas Soshea BenMaier & Eastham

From: Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>> Sent: Tuesday, September 13, 2022 8:33 AM

To: Kelly Haas <<u>Khaas@sbsblaw.com</u>>

Cc: James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>; Mahabeer, Niree

<<u>niree.mahabeer@vgrouplimited.com</u>>; Steve Cunningham IMC <<u>scunningham@independentmaritime.com</u>>; Victor Johansson <<u>Victor Johansson@swedishclub.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>) <<u>stephanie@hilderlaw.com</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>; Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>; Christoffersen, Dag <<u>Dag Christoffersen@vships.no</u>>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>>; Avdal, Gjermund <<u>Gjermund.Avdal@vships.no</u>>; 'jk' <<u>ik@swiftbulk.com</u>>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

#### Kind Regards,

Patrik Del Mestre Claims Executive, P&I Team Sweden

The Swedish Club Tel: +46 31 638 419 Mobile: +46 730 644 663 Patrik.DelMestre@swedishclub.com www.swedishclub.com



### in 😏

From: Nordstrand, Ronny <ronny.nordstrand@vships.no> Sent: den 13 september 2022 10:44

To: 'jk' <jk@swiftbulk.com>; Laiho, Vesa <<u>vesa laiho@vships.no</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>; Cc: James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>; Mahabeer, Niree <nirce.mahabeer@vgrouplimited.com>; Steve Cunningham IMC <scunningham@independentmaritime.com>; Victor Johansson <<u>Victor.Johansson@swedishclub.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>) <<u>stephanie@hilderlaw.com</u>>; Patrik Del Mestre <Patrik.DelMestre@swedishclub.com>; Kelly Haas <Khaas@sbsblaw.com>; Stefanos Kasselakis <sk@swiftbulk.com>; Christoffersen, Dag <<u>Dag.Christoffersen@vships.com</u>>; Avdal, Gjermund <<u>Gjermund Avdal@vships.no</u>>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Best Regards **Ronny Nordstrand** Senior Fleet Manager - V. Ships Norway As agent and manager only for and on behalf of the Owner

Tel: +47 23 25 10 00 Direct: +47 23 25 10 21 Mob: +47 917 79 206 Email: ronny nordstrand@vships.no



From: jk <ik@swiftbulk.com> Sent: 13 September 2022 04:53 To: Nordstrand, Ronny < ronny.nordstrand@vships.no>; Laiho, Vesa < vesa.laiho@vships.no>; Swift Winchester VCG

#### <tech.swiftwinchester@vships.no>

Cc: James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>; Mahabeer, Niree

<niree.mahabeer@vgrouplimited.com>; Nordstrand, Ronny <ronny.nordstrand@vships.no>; Steve Cunningham IMC

<scunningham@independentmaritime.com>; Victor Johansson <Victor.Johansson@swedishclub.com>; Robert Klawetter

<<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Stephanie K. McGuire

(stephanie@hilderlaw.com) <stephanie@hilderlaw.com>; Patrik Del Mestre <Patrik.DelMestre@swedishclub.com>; Kelly Haas

<<u>Khaas@sbsblaw.com</u>>; Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>; Christoffersen, Dag <<u>Dag Christoffersen@vships.com</u>>; Avdal, Gjermund <<u>Gjermund Avdal@vships.np</u>>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

J. Karystios SwiftBulk | SwiftTankers jk@swiftbulk.com ----- Original message ------From: Kelly Haas <Khaas@sbsblaw.com> Date: 9/13/22 04:43 (GMT+02:00) To: Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>, Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>> Cc: James Bailey <]Bailey@sbsb-eastham.com>, Tankers Swiftbulk <tankers@swiftbulk.com>, Swift Winchester VCG <tech.swiftwinchester@vships.no>, John Karystios <jk@swiftbulk.com>, "Avdal, Gjermund" <Gjermund.Avdal@vships.no>, "Christoffersen, Dag. < Dag. Christoffersen@vships.com>, niree.mahabeer@vgrouplimited.com, "Laiho, Vesa" < vesa.laiho@vships.no>, "Nordstrand, Ronny" <ronny.nordstrand@vships.no>, Steve Cunningham IMC <scunningham@independentmaritime.com>, Victor Johansson < Victor. Johansson@swedishclub.com>, Robert Klawetter < RKlawetter@sbsb-eastham.com>, Dylan Hoke < < href="mailto:dhoke@sbsblaw.com">dhoke@sbsblaw.com</a>, Tate Williams <tate@hilderlaw.com>, "Stephanie K. McGuire (stephanie@hilderlaw.com)" <stephanie@hilderlaw.com> Subject: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682 Dear Stefanos and Patrik, Please accept the following status report regarding the information received today.

Best regards,

Kelly M. Haas Partner



Schouest Bamdas Soshea BenMaier & Eastham

1001 McKinney Street | Suite 1400 Houston | Texas | 77002 (713) 893-6168 | Direct (832) 465-1176 | Cell (713) 574-2942 | Fax khaas@sbsb-eastham.com

The information transmitted, including any attachments, is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is prohibited, and all liability arising therefrom is disclaimed. If you received this in error, please contact the sender and delete the material from any computer. Thank you.

This message is intended solely for the addressee and may contain confidential information. If you have received this message in error, please send it back to us, and immediately and permanently delete it. Do not use, copy or disclose the information contained in this message or in any attachment.

The Swedish Club processas personal data in accordance with a privacy policy which can be found  $\underline{\text{here}}$ 

CONFIDENTIAL. This e-mail message and any attachments are private communication and may contain confidential, or otherwise legally privileged information meant solicity for the intended recipient. If you are not the intended recipient you are hereby notified that any use dissemination, distribution or copying of this communication is strictly prohibited. Please notify the sender immediately by replying to this message the delete the e-mail and any attachments from your system Thank you.

Stefanos Kasselakis SwiftBulk | SwiftTankers 299 Park Avenue, 13th Floor New York, New York 10171 +1 212-446-5415 (USA) +30 210-933-5622 (GR) sk@swiftbulk.com

客冰米洋水台意味大学会学术大学者学术大学者并从有些有些有关的的关系,在这些是是有关系的是不不能与这些的事件不是是有关的关系的的方式的都有关的的不同的有关的的有关的的有关的的有关的的有关的的有关的的有关的

This message and any attachments may contain confidential or privileged information and are only for the use of the intended recipient of this message. If you are not the intended recipient, please notify the Blank Rome LLP or Blank Rome Government Relations LLC sender by return email, and delete or destroy this and all copies of this message and all attachments. Any unauthorized disclosure, use, distribution, or reproduction of this message or any attachments is prohibited and may be unlawful.

### Exhibit 9 *In camera*

From:	Kelly Haas
то:	Grasso, Jeanne; Stefanos Kasselakis
Cc:	Avdal. Glemund; Carison. Kiestan; Christoffersen. Dag; Herschaft, Jeremy A.; James Bailey; Kwok, Siew; Laiho, Yesa; Linsin, Greg F.; Mahabeer. Niree; Nordstrand, Ronny: Paring Del Mestre; Rifklind. Neil; Nobert Klawetter; Stephanie K. McGuire (stephanie/ahliderlaw.com); Steve Cunningham IMC; Swift Winchester VCG; Tankers Swiftbulk; Tate Williams; Victor Johansson; Ik
Subject:	RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682
Date: Attachments:	Wednesday, September 14, 2022 9:15:00 AM

Dear All,

Best regards,

### Kelly M. Haas

D: 713.893.6168 | M: 832.465.1176



Schouest Bamdas Soshea BenMaier & Eastham

From: Grasso, Jeanne <jeanne.grasso@blankrome.com> Sent: Tuesday, September 13, 2022 3:54 PM

Ter Cheferen Kanadalia al Que Ghall anno Kalla Una akta

To: Stefanos Kasselakis <sk@swiftbulk.com>; Kelly Haas <Khaas@sbsblaw.com>

Cc: Avdal, Gjermund <Gjermund.Avdal@vships.no>; Carlson, Kierstan <kierstan.carlson@blankrome.com>; Christoffersen, Dag <Dag.Christoffersen@vships.com>; Herschaft, Jeremy A. <jeremy.herschaft@blankrome.com>; James Bailey <JBailey@sbsb-eastham.com>; Kwok, Siew <SKwok@tiptreeinc.com>; Laiho, Vesa <vesa.laiho@vships.no>; Linsin, Greg F. <greg.linsin@blankrome.com>; Mahabeer, Niree <niree.mahabeer@vgrouplimited.com>; Nordstrand, Ronny <ronny.nordstrand@vships.no>; Patrik Del Mestre

<Patrik.DelMestre@swedishclub.com>; Rifkind, Neil <NRifkind@tiptreeinc.com>; Robert Klawetter <RKlawetter@sbsb-eastham.com>; Stephanie K. McGuire (stephanie@hilderlaw.com) <stephanie@hilderlaw.com>; Steve Cunningham IMC

<scunningham@independentmaritime.com>; Swift Winchester VCG <tech.swiftwinchester@vships.no>; Tankers Swiftbulk <tankers@swiftbulk.com>; Tate Williams <tate@hilderlaw.com>; Victor Johansson <Victor.Johansson@swedishclub.com>; jk <jk@swiftbulk.com>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Jeanne M. Grasso | BLANKROME 1825 Eye Street NW | Washington, DC 20006-5403 Tel: +1 202.772.5927 | Mob: +1 202.431.2240 | Email: jeanne.grasso@blankrome.com

Winner of Lloyd's List 2019 Maritime Legal Services Award

BLANK ROME COVID-19 Task Force Page

From: Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>

Sent: Tuesday, September 13, 2022 4:49 PM To: Kelly Haas <<u>Khaas@sbsblaw.com</u>>

**Cc:** Avdal, Gjermund <<u>Gjermund.Avdal@vships.no</u>>; Carlson, Kierstan <<u>kierstan.carlson@blankrome.com</u>>; Christoffersen, Dag <<u>Dag.Christoffersen@vships.com</u>>; Grasso, Jeanne <<u>jeanne.grasso@blankrome.com</u>>; Herschaft, Jeremy A. <<u>jeremy.herschaft@blankrome.com</u>>; James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Kwok, Siew <<u>SKwok@tiptreeinc.com</u>>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Linsin, Greg F. <<u>greg.linsin@blankrome.com</u>>; Mahabeer, Niree <<u>piree.mahabeer@vgrouplimited.com</u>>;

Nordstrand, Ronny <<u>ronny nordstrand@vships.no</u>>; Patrik Del Mestre <<u>Patrik DelMestre@swedishclub.com</u>>; Rifkind, Neil <<u>NRifkind@tiptreeinc.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>); <u>stephanie@hilderlaw.com</u>>; Steve Cunningham IMC <<u>scunningham@independentmaritime.com</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Victor Johansson <<u>Victor.Johansson@swedishclub.com</u>>; jk <<u>jk@swiftbulk.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Victor Johansson

Subject: Re: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Thanks for the update, Kelly.

1

Copying the Blank Rome and in house team here as well.

On Tue, Sep 13, 2022 at 16:44 Kelly Haas <<u>Khaas@sbsblaw.com</u>> wrote:


Best regards,

Kelly M. Haas D: 713.893.6168 | M: 832.465.1176

	Schouest
<u>/SB</u>	Bamdas
<b>SB</b>	Soshea
	BenMaier
EASTHAM	& Eastham

From: Patrik Del Mestre <<u>Patrik DelMestre@swedishclub.com</u>> Sent: Tuesday, September 13, 2022 8:33 AM

To: Kelly Haas <<u>Khaas@sbsblaw.com</u>>

Cc: James Bailey <JBailey@sbsb-eastham.com>; Tankers Swiftbulk <tankers@swiftbulk.com>; Mahabeer, Niree

<<u>niree:mahabeer@vgrouplimited.com</u>>; Steve Cunningham IMC <<u>scunningham@independentmaritime.com</u>>; Victor Johansson <<u>Victor.lohansson@swedishclub.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>) <<u>stephanie@hilderlaw.com</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>; Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>; Christoffersen, Dag <<u>Dag.Christoffersen@vships.no</u>>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>>; Avdal, Gjermund <<u>Gjermund.Avdal@vships.no</u>>; 'jk' <<u>jk@swiftbulk.com</u>>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Kind Regards,

Patrik Del Mestre Claims Executive, P&I Team Sweden

The Swedish Club Tel: +46 31 638 419 Mobile: +46 730 644 663 Patrik DelMestre@swedishclub.com www.swedishclub.com





From: Nordstrand, Ronny <ronny.nordstrand@yships.no>

Sent: den 13 september 2022 10:44

To: 'jk' <<u>ik@swiftbulk.com</u>>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>

Cc: James Bailey <JBailey@sbsb-eastham.com>; Tankers Swiftbulk <tankers@swiftbulk.com>; Mahabeer, Niree

<<u>niree.mahabeer@vgrouplimited.com</u>
; Steve Cunningham IMC <<u>scunningham@independentmaritime.com</u>
; Victor Johansson

<<u>Victor.Johansson@swedishclub.com</u>
; Robert Klawetter <<u>Rklawetter@sbsb-eastham.com</u>
; Dylan Hoke <<u>dhoke@sbsblaw.com</u>
; Tate
Williams <<u>tate@hilderlaw.com</u>
; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>) <<u>stephanie@hilderlaw.com</u>
; Patrik Del Mestre
<<u>Patrik.DelMestre@swedishclub.com</u>
; Kelly Haas <<u>Khaas@sbsblaw.com</u>
; Stefanos Kasselakis <<u>sk@swiftbulk.com</u>
; Christoffersen, Dag
<<u>Dag.Christoffersen@vships.com</u>
; Avdal, Gjermund <<u>Gjermund Avdal@vships.no</u>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

John

Best Regards Ronny Nordstrand Senior Fleet Manager – V. Ships Norway As agent and manager only for and on behalf of the Owner

Tel: +47 23 25 10 00 Direct: +47 23 25 10 21 Mob: +47 917 79 206 Email: ronny.nordstrand@yships.no



From: jk <jk@swiftbulk.com>

Sent: 13 September 2022 04:53

To: Nordstrand, Ronny <<u>ronny.nordstrand@yships.no</u>>; Laiho, Vesa <<u>vesa.laiho@yships.no</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@yships.no</u>>

Cc: James Bailey < JBailey@sbsb-eastham.com>; Tankers Swiftbulk < tankers@swiftbulk.com>; Mahabeer, Niree

<niree.mahabeer@vgrouplimited.com>; Nordstrand, Ronny <ronny.nordstrand@vships.no>; Steve Cunningham IMC

<scunningham@independentmaritime.com>; Victor Johansson <Victor.Johansson@swedishclub.com>; Robert Klawetter

<<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Stephanie K. McGuire

(stephanie@hilderlaw.com) <stephanie@hilderlaw.com>; Patrik Del Mestre <Patrik.DelMestre@swedishclub.com>; Kelly Haas

<<u>Khaas@sbsblaw.com</u>>; Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>; Christoffersen, Dag <<u>Dag.Christoffersen@vships.com</u>>; Avdal, Gjermund <<u>Gjermund.Avdai@vships.no</u>>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

. Karystios
wiftBulk   SwiftTankers k@swiftbulk.com
Original message
rom: Kelly Haas < <u>Khaas@sbsblaw.com</u> > ate: 9/13/22 04:43 (GMT+02:00)
b: Stefanos Kasselakis < <u>sk@swiftbulk.com</u> >, Patrik Del Mestre < <u>Patrik.DelMestre@swedishclub.com</u> >
c: James Bailey < <u>JBailey@sbsb-eastham.com</u> >, Tankers Swiftbulk < <u>tankers@swiftbulk.com</u> >, Swift Winchester VCG
tech.swiftwinchester@vships.no>, John Karystios < <a href="http://www.ikestermund">http://www.ikestermund.avdal@vships.no</a> , "Christoffersen,
ag" < Dag. Christoffersen@vships.com>, niree.mahabeer@vgrouplimited.com, "Laiho, Vesa" < <u>vesa.laiho@vships.no</u> >, "Nordstrand, Ronny"
<u>ronnv.nordstrand@vships.no</u> >, Steve Cunningham IMC < <u>scunningham@independentmaritime.com</u> >, Victor Johansson <u>Victor.Johansson@swedishclub.com</u> >, Robert Klawetter < <u>RKlawetter@sbsb-eastham.com</u> >, Dylan Hoke < <u>dhoke@sbsblaw.com</u> >, Tate
victor Jonanson executive sweeting control of the second
ubject: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682
Dear Stefanos and Patrik,
ease accept the following status report regarding the information received today.
test regards,
Kelly M. Haas

Partner



Schouest Bamdas Soshea BenMaier & Eastham

1001 McKinney Street | Suite 1400 Houston | Texas | 77002 (713) 893-6168 | Direct (832) 465-1176 | Cell (713) 574-2942 | Fax khaas@sbsb-eastham.com

The information transmitted, including any attachments, is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is prohibited, and all liability arising therefrom is disclaimed. If you received this in error, please contact the sender and delete the material from any computer. Thank you.

This message is intended solely for the addressee and may contain confidential information. If you have received this message in error, please send it back to us, and immediately and permanently delete it. Do not use, copy or disclose the information contained in this message or in any attachment.

The Swedish Club processes personal data in accordance with a privacy policy which can be found here

CONFIDENTIAL. This e-mail message and any attachments are private communication and may contain confidential, or otherwise legally privileged information meant solarly for the intended recipient if you are not the intended recipient, you are hereby notified that any use dissemination distribution or coaying of this communication is stridly prohibited. Please notify the sender immediately by replying to this message, then delete the e-mail and any attachments from your system. Thank you

### Stefanos Kasselakis SwiftBulk | SwiftTankers

299 Park Avenue, 13th Floor New York, New York 10171 +1 212-446-5415 (USA) +30 210-933-5622 (GR) sk@swiftbulk.com

\*\*\*\*\*\*\*\*\*\*\*\*\*\*

This message and any attachments may contain confidential or privileged information and are only for the use of the intended recipient of this message. If you are not the intended recipient, please notify the Blank Rome LLP or Blank Rome Government Relations LLC sender by

return email, and delete or destroy this and all copies of this message and all attachments. Any unauthorized disclosure, use, distribution, or reproduction of this message or any attachments is prohibited and may be unlawful.

### Exhibit 10 In camera

From:	Kelly Haas	
To:	Patrik Del Mestre; Steve Cunningham IMC	
Cc:	Robert Klawetter; James Bailey; Victor Johansson	
Subject:	RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682	
Date:	Wednesday, September 14, 2022 9:17:00 AM	
Attachments:	image005.png image006.png image007.png	

Dear Patrik,

Understood. We will monitor the situation and will report any new information, but will not play a large role without your instruction.

### Kelly M. Haas D: 713.893.6168 | M: 832.465.1176



From: Patrik Del Mestre <Patrik.DelMestre@swedishclub.com>
Sent: Wednesday, September 14, 2022 9:13 AM
To: Kelly Haas <Khaas@sbsblaw.com>; Steve Cunningham IMC
<scunningham@IndependentMaritime.com>
Cc: Robert Klawetter <RKlawetter@sbsb-eastham.com>; James Bailey <JBailey@sbsb-eastham.com>; Victor Johansson <Victor.Johansson@swedishclub.com>
Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Dear Kelly, Dear Steve,

Kind Regards,

Patrik Del Mestre Claims Executive, P&I Team Sweden



The Swedish Club Tel: +46 31 638 419 Mobile: +46 730 644 663 Patrik.DelMestre@swedishclub.com www.swedishclub.com

### in 🎔

From: Kelly Haas <<u>Khaas@sbsblaw.com</u>> Sent: den 13 september 2022 16:26 To: Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>> Cc: Steve Cunningham IMC <<u>scunningham@IndependentMaritime.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Victor Johansson <<u>Victor.Johansson@swedishclub.com</u>> Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682


Best regards,

Kelly M. Haas D: 713.893.6168 | M: 832.465.1176



Schouest Bamdas Soshea BenMaier & Eastham

From: Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>>
Sent: Tuesday, September 13, 2022 8:34 AM
To: Kelly Haas <<u>Khaas@sbsblaw.com</u>>
Cc: Steve Cunningham IMC <<u>scunningham@IndependentMaritime.com</u>>; Robert Klawetter
<<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Victor Johansson
<<u>Victor.Johansson@swedishclub.com</u>>
Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682



Kind Regards,

Patrik Del Mestre Claims Executive, P&I Team Sweden

The Swedish Club Tel: +46 31 638 419 Mobile: +46 730 644 663 Patrik.DelMestre@swedishclub.com www.swedishclub.com





The Swedish Club processes personal data in accordance with a privacy policy which can be found  $\underline{here}$ 

CONFIDENTIAL: This e-mail message and any attachments are private communication and may contain confidential, or otherwise legally privileged information meant solely for the intended recipient. If you are not the intended recipient, you are hereby notified that any use, dissemination, distribution or copying of this communication is strictly prohibited. Please notify the sender immediately by replying to this message, then delete the e-mail and any attachments from your system. Thank you.

The Swedish Club processes personal data in accordance with a privacy policy which can be found  $\underline{here}$ 

CONFIDENTIAL: This e-mail message and any attachments are private communication and may contain confidential, or otherwise legally privileged information meant solely for the intended recipient. If you are not the intended recipient, you are hereby notified that any use, dissemination, distribution or copying of this communication is strictly prohibited. Please notify the sender immediately by replying to this message, then delete the e-mail and any attachments from your system. Thank you.

•

-----

## Exhibit 11 *In camera*

### Kelly Haas

From:	master.v7rf3@globeemail.com	
Sent:	Thursday, September 15, 2022 9:07 AM	
To:	'Nordstrand, Ronny'; 'Barstad, Per Harald'; 'Laiho, Vesa'	
Cc:	'Bratanov, Damian'; tate@hilderlaw.com; 'Ball, Sam'; hseq@vships.no; acardona@register-iri.com;	
	Kelly Haas; mp.sing@brookersbell.com; 'Nasa Ops'; 'NASA Beaumont'	
Subject:	Swift Winchester : USCG Letter	
Attachments:	achments:	

You don't often get email from master.v7rf3@globeemail.com. Learn why this is important

Best regards, Capt. Aleksei Kharitonov Master of MT "Swift Winchester" Email: <u>master.v7rf3@globeemail.com</u> Tel Bridge: +870 773 802 025 Tel Master: +44 2036951546 Tlx Inmarsat C: 453834067/ 453834068

### Exhibit 12 *In camera*

From:	Kelly Haas
То:	Victor Johansson; Patrik Del Mestre; Avdal, Gjermund; Carlson, Kierstan; Christoffersen, Dag; Herschaft, Jeremy A; James Balley; Kwok, Siew; Laiho, Vesa; Linsin, Greg E; Mahabeer, Niree; Nordstrand, Ronny; Patrik Del Mestre; Rifkind, Neij; Robert, Klavetter; Stephanie K, McGuire (stephanie@hilderlaw.com); Steve Cunningham INC; Swift Wirchester VCG; Tankers Swiftbulk; Tate Williams; ik; Grasso, Jeanne; Stefanos Kasselakis
Subject:	RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682
Date:	Thursday, September 15, 2022 10:04:00 AM
Attachments:	image002.png image003.png image004.png
2. Y	

I will stand down until further notice.

### Kelly M. Haas

D: 713.893.6168 | M: 832.465.1176



Schouest Bamdas Soshea BenMaier & Eastham

From: Victor Johansson <Victor.Johansson@swedishclub.com>

Sent: Thursday, September 15, 2022 10:01 AM

To: Kelly Haas <Khaas@sbsblaw.com>; Patrik Del Mestre <Patrik.DelMestre@swedishclub.com>; Avdal, Gjermund

<Gjermund.Avdal@vships.no>; Carlson, Kierstan <kierstan.carlson@blankrome.com>; Christoffersen, Dag <Dag.Christoffersen@vships.com>; Herschaft, Jeremy A. <jeremy.herschaft@blankrome.com>; James Bailey <JBailey@sbsb-eastham.com>; Kwok, Siew

<SKwok@tiptreeinc.com>; Laiho, Vesa <vesa.laiho@vships.no>; Linsin, Greg F. <greg.linsin@blankrome.com>; Mahabeer, Niree

<niree.mahabeer@vgrouplimited.com>; Nordstrand, Ronny <ronny.nordstrand@vships.no>; Patrik Del Mestre

<Patrik.DelMestre@swedishclub.com>; Rifkind, Neil <NRifkind@tiptreeinc.com>; Robert Klawetter <RKlawetter@sbsb-eastham.com>; Stephanie K. McGuire (stephanie@hilderlaw.com) <stephanie@hilderlaw.com>; Steve Cunningham IMC

<scunningham@independentmaritime.com>; Swift Winchester VCG <tech.swiftwinchester@vships.no>; Tankers Swiftbulk

<tankers@swiftbulk.com>; Tate Williams <tate@hilderlaw.com>; jk <jk@swiftbulk.com>; Grasso, Jeanne <jeanne.grasso@blankrome.com>; Stefanos Kasselakis <sk@swiftbulk.com>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Best regards,

Victor Johansson Head of Claims - P&I, FD&D Team Sweden

The Swedish Club Tel: +46 31 638 454 Mobile: +46 702 002 507 <u>Victor.Johansson@swedishclub.com</u> www.swedishclub.com





#### From: Kelly Haas <<u>Khaas@sbsblaw.com</u>>

Sent: den 15 september 2022 16:17

To: Patrik Del Mestre <<u>Patrik DelMestre@swedishclub.com</u>; Victor Johansson <<u>Victor Johansson@swedishclub.com</u>; Avdal, Gjermund <<u>Gjermund Avdal@vships.no</u>; Carlson, Kierstan <<u>kierstan.carlson@blankrome.com</u>; Christoffersen, Dag <<u>Dag.Christoffersen@yships.com</u>; Herschaft, Jeremy A. <<u>jeremy.herschaft@blankrome.com</u>; James Bailey <<u>JBailey@sbsb-eastham.com</u>; Kwok, Siew <<u>SKwok@tiptreeinc.com</u>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>; Linsin, Greg F. <<u>greg.linsin@blankrome.com</u>; Mahabeer, Niree <<u>niree.mahabeer@vgrouplimited.com</u>; Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>; Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>; Rifkind, Neil <<u>NRifkind@tiptreeinc.com</u>; Robert Klawetter <<u>Rklawetter@sbsb-eastham.com</u>; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>) <<u>stephanie@hilderlaw.com</u>; Steve Cunningham IMC <<u>scunningham@independentmaritime.com</u>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>; Tate Williams <<u>tate@hilderlaw.com</u>; Victor Johansson <<u>Victor Johansson@swedishclub.com</u>; jk <<u>jk@swiftbulk.com</u>; Grasso, Jeanne <u>eanne.grasso@blankrome.com</u>; Stefanos Kasselakis <<u>sk@swiftbulk.com</u>> Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Best regards,

Kelly M. Haas D: 713.893.6168 | M: 832.465.1176



Schouest Bamdas Soshea BenMaier & Eastham

From: Kelly Haas

Sent: Wednesday, September 14, 2022 9:16 AM

To: Grasso, Jeanne <ieanne.grasso@blankrome.com>; Stefanos Kasselakis <sk@swiftbulk.com>

Cc: Avdal, Gjermund <<u>Gjermund,Avdal@vships.no</u>>; Carlson, Kierstan <<u>kierstan.carlson@blankrome.com</u>>; Christoffersen, Dag <<u>Dag,Christoffersen@vships.com</u>>; Herschaft, Jeremy A. <<u>jeremy.herschaft@blankrome.com</u>>; James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Kwok, Siew <<u>SKwok@tiptreeinc.com</u>>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Linsin, Greg F. <<u>greg.linsin@blankrome.com</u>>; Mahabeer, Niree <<u>niree.mahabeer@vgrouplimited.com</u>>; Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>>; Patrik Del Mestre

<<u>Patrik.DelMestre@swedishclub.com</u>>; Rifkind, Neil <<u>NRifkind@tiptreeinc.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>) <<u>stephanie@hilderlaw.com</u>>; Steve Cunningham IMC

<scunningham@independentmaritime.com>; Swift Winchester VCG <tech.swiftwinchester@vships.no>; Tankers Swiftbulk

<<u>tankers@swiftbulk.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Victor Johansson <<u>Victor Johansson@swedishclub.com</u>>; jk <<u>jk@swiftbulk.com</u>>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Best regards,

Kelly M. Haas D: 713.893.6168 | M: 832.465.1176



From: Grasso, Jeanne < ieanne.grasso@blankrome.com>

Sent: Tuesday, September 13, 2022 3:54 PM

To: Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>; Kelly Haas <<u>Khaas@sbsblaw.com</u>>

Cc: Avdal, Gjermund <<u>Gjermund Avdal@vships.no</u>>; Carlson, Kierstan <<u>kierstan.carlson@blankrome.com</u>>; Christoffersen, Dag <<u>Dag Christoffersen@vships.com</u>>; Herschaft, Jeremy A. <<u>jeremv.herschaft@blankrome.com</u>>; James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Kwok, Siew <<u>SKwok@tiptreeinc.com</u>>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Linsin, Greg F. <<u>greg.linsin@blankrome.com</u>>; Mahabeer, Niree <<u>niree\_mahabeer@vgrouplimited.com</u>>; Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>>; Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>>; Rifkind, Neil <<u>NRifkind@tiptreeinc.com</u>>; Robert Klawetter@sbsb-eastham.com>; Stephanie@hilderlaw.com</u>>; Steve Cunningham IMC

<<u>scunningham@independentmaritime.com</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Victor Johansson <<u>Victor Johansson@swedishclub.com</u>>; jk <<u>jk@swiftbulk.com</u>>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Jeanne M. Grasso | BLANKROME 1825 Eye Street NW | Washington, DC 20006-5403 Tel: +1 202.772.5927 | Mob: +1 202.431.2240 | Email: jeanne.grasso@blankrome.com

Winner of Lloyd's List 2019 Maritime Legal Services Award

BLANK ROME COVID-19 Task Force Page

From: Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>

Sent: Tuesday, September 13, 2022 4:49 PM

To: Kelly Haas <Khaas@sbsblaw.com>


Cc: Avdal, Gjermund <<u>Gjermund, Avdal@vships.no</u>>; Carlson, Kierstan <<u>kierstan.carlson@blankrome.com</u>>; Christoffersen, Dag <<u>Dag.Christoffersen@vships.com</u>>; Grasso, Jeanne <<u>ieanne.grasso@blankrome.com</u>>; Herschaft, Jeremy A. <<u>ieremy.herschaft@blankrome.com</u>>; James Bailey <<u>IBailey@sbsb-eastham.com</u>>; Kwok, Siew <<u>SKwok@tiptreeinc.com</u>>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Linsin, Greg F. <<u>greg.linsin@blankrome.com</u>>; Mahabeer, Niree <<u>niree.mahabeer@vgrouplimited.com</u>>; Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>>; Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>>; Rifkind, Neil <<u>NRifkind@tiptreeinc.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>) <<u>stephanie@hilderlaw.com</u>>; Steve Cunningham IMC <<u>scunningham@independentmaritime.com</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>; Tankers Swiftbulk.com>; Tate Williams <<u>tate@hilderlaw.com</u>>; Victor Johansson <<u>Victor.Johansson@swedishclub.com</u>>; Jk <<u>ik@swiftbulk.com</u>>

Subject: Re: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Thanks for the update, Kelly.

Copying the Blank Rome and in house team here as well.

On Tue, Sep 13, 2022 at 16:44 Kelly Haas <<u>Khaas@sbsblaw.com</u>> wrote:



To: Kelly Haas < Khaas@sbsblaw.com>

Cc: James Bailey <JBailey@sbsb-eastham.com>; Tankers Swiftbulk <tankers@swiftbulk.com>; Mahabeer, Niree

<<u>niree.mahabeer@vgrouplimited.com</u>>; Steve Cunningham IMC <<u>scunningham@independentmaritime.com</u>>; Victor Johansson <<u>Victor.Johansson@swedishclub.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>) <<u>stephanie@hilderlaw.com</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>; Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>; Christoffersen, Dag <<u>Dag.Christoffersen@vships.no</u>>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Nordstrand, Ronny <<u>ronnv.nordstrand@vships.no</u>>; Avdal, Gjermund <<u>Gjermund.Avdal@vships.no</u>>; 'jk' <jk@swiftbulk.com>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Dear Kelly,



#### Kind Regards,

Patrik Del Mestre Claims Executive, P&I Team Sweden

The Swedish Club Tel: +46 31 638 419 Mobile: +46 730 644 663 Patrik.DelMestre@swedishclub.com



### in У

From: Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>> Sent: den 13 september 2022 10:44

To: 'jk' <<u>ik@swiftbulk.com</u>>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>> Cc: James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>; Mahabeer, Niree

<<u>niree.mahabeer@vgrouplimited.com</u>>; Steve Cunningham IMC <<u>scunningham@independentmaritime.com</u>>; Victor Johansson
<u>Victor Johansson@swedishclub.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate
Williams <<u>tate@hilderlaw.com</u>>; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>) <<u>stephanie@hilderlaw.com</u>>; Patrik Del Mestre
<u>Patrik.DelMestre@swedishclub.com</u>>; Kelly Haas <<u>Khaas@sbsblaw.com</u>>; Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>; Christoffersen, Dag<<<u>Dag.Christoffersen@vships.com</u>>; Avdal, Gjermund <<u>Gjermund Avdal@vships.no</u>>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

Best Regards Ronny Nordstrand Senior Fleet Manager – V. Ships Norway As agent and manager only for and on behalf of the Owner

Tel: +47 23 25 10 00 Direct: +47 23 25 10 21 Mob: +47 917 79 206 Email: <u>ronny.nordstrand@yships.no</u>



From: jk <jk@swiftbulk.com>

Sent: 13 September 2022 04:53

To: Nordstrand, Ronny <<u>ronny.nordstrand@vships.no</u>>; Laiho, Vesa <<u>vesa.laiho@vships.no</u>>; Swift Winchester VCG <<u>tech.swiftwinchester@vships.no</u>>

Cc: James Bailey <<u>JBailey@sbsb-eastham.com</u>>; Tankers Swiftbulk <<u>tankers@swiftbulk.com</u>>; Mahabeer, Niree <<u>niree\_mahabeer@vgrouplimited.com</u>>; Nordstrand, Ronny <<u>ronny\_nordstrand@vships.no</u>>; Steve Cunningham IMC <<u>scunningham@independentmaritime.com</u>>; Victor Johansson <<u>Victor\_Johansson@swedishclub.com</u>>; Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>; Dylan Hoke <<u>dhoke@sbsblaw.com</u>>; Tate Williams <<u>tate@hilderlaw.com</u>>; Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>) < <u>stephanie@hilderlaw.com</u>>; Patrik Del Mestre <<u>Patrik.DelMestre@swedishclub.com</u>>; Kelly Haas <<u>Khaas@sbsblaw.com</u>>; Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>; Christoffersen, Dag <<u>Dag.Christoffersen@vships.com</u>>; Avdal, Gjermund <<u>Gjermund.Avdal@vships.no</u>>

Subject: RE: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

J. Karystios SwiftBulk | SwiftTankers jk@swiftbulk.com

----- Original message ------

From: Kelly Haas <<u>Khaas@sbsblaw.com</u>>

Date: 9/13/22 04:43 (GMT+02:00)

To: Stefanos Kasselakis <<u>sk@swiftbulk.com</u>>, Patrik Del Mestre <<u>Patrik DelMestre@swedishclub.com</u>>

Cc: James Bailey <JBailey@sbsb-eastham.com>, Tankers Swiftbulk <tankers@swiftbulk.com>, Swift Winchester VCG

<<u>tech.swiftwinchester@vships.no</u>>, John Karystios <<u>ik@swiftbulk.com</u>>, "Avdal, Gjermund" <<u>Gjermund.Avdal@vships.no</u>>, "Christoffersen, Dag" <<u>Dag.Christoffersen@vships.no</u>>, niree.mahabeer@vgrouplimited.com, "Laiho, Vesa" <<u>vesa.laiho@vships.no</u>>, "Nordstrand, Ronny" <<u>ronny.nordstrand@vships.no</u>>, Steve Cunningham IMC <<u>scunningham@independentmaritime.com</u>>, Victor Johansson

<<u>Victor Johansson@swedishclub.com</u>>, Robert Klawetter <<u>RKlawetter@sbsb-eastham.com</u>>, Dylan Hoke <<u>dhoke@sbsblaw.com</u>>, Tate Williams <<u>tate@hilderlaw.com</u>>, "Stephanie K. McGuire (<u>stephanie@hilderlaw.com</u>)" <<u>stephanie@hilderlaw.com</u>>

Subject: STATUS UPDATE - Swift Winchester - Detained by USCG - TSC ref: 20222682

st regards, elly M. Haas	
SB	Schouest Bamdas
SB	Soshea BenMaiei
D1 McKinney Street   Suite 1400 uston   Texas   77002 13) 893-6168   Direct	& Easthar

khaas@sbsb-eastham.com

The information transmitted, including any attachments, is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is prohibited, and all liability arising therefrom is disclaimed. If you received this in error, please contact the sender and delete the material from any computer. Thank you.

This message is intended solely for the addressee and may contain confidential information. If you have received this message in error, please send it back to us, and immediately and permanently delete it. Do not use, copy or disclose the information contained in this

message or in any attachment.

The Swedish Club processes personal data in accordance with a privacy policy which can be found  $\underline{here}$ 

CONFIDENTIAL: This e-mail message and any attechments are private communication and may contein confidential, or otherwise legally privileged information meant solely for the intended recipient. If you are not the intended recipient, you are hereby notified that any use, dissemination, distribution or copying of this communication is strictly prohibited. Please notify the sender immediataly by raphing to this message, there delete the e-mail and any attachments from your system . Thank you.

#### Stefanos Kasselakis SwiftBulk | SwiftTankers 299 Park Avenue, 13th Floor New York, New York 10171 +1 212-446-5415 (USA) +30 210-933-5522 (GR) sk@swiftbulk.com

This message and any attachments may contain confidential or privileged information and are only for the use of the intended recipient of this message. If you are not the intended recipient, please notify the Blank Rome LLP or Blank Rome Government Relations LLC sender by return email, and delete or destroy this and all copies of this message and all attachments. Any unauthorized disclosure, use, distribution, or reproduction of this message or any attachments is prohibited and may be unlawful.

**你我们太爱你的我说我的我看我要要要的我都要我要要我要要我要要我在那些我的的这些是不是这些的人们的那些人人的是你不能是我们的人,我们还是这些人,我们还是不是这么,我们还是这些人,我们还是这些人,我们还是这些人,我们还是这些人,我们还是** 

The Swedish Club processes personal data in accordance with a privacy policy which can be found  $\underline{here}$ 

CONFIDENTIAL: This e-mail message and any attachments are private communication and may contain confidential, or otherwise legally privileged information meant solarly for the intended racipient. If you are not the intended racipient, you are hereby notified that any use. diseenination, distribution or copying of this communication is strictly prohibited. Prease notify the sender immediately by replying to this message, than delete the e-mail and any attachments from your system. Thank you.