
Main File No. 201311438 Page #24

Comparable Photo Page

Borrower/Client	Robert & Betty Marshall							
Property Address	30393 Upper Bear Creek							
City	Evergreen	County	Jefferson	State	co	Zip Code	80439	
1 ender	Bank Of The West							



Comparable 7

32834 Upper Bear Creek Road Prox. to Subject 1.61 miles W Sales Price 795,000 Gross Living Area 3,218 Total Rooms Total Bedrooms 5 Total Bathrooms 3.0 Location N;Mountain; B;Wtr;Mtn View 4.77 ac Site Quality Q3 65 Age

Comparable 8


Prox. to Subject Sales Price Gross Living Area Total Rooms Total Bedrooms Total Bathrooms Location View Site Quality Age

Comparable 9

Prox. to Subject Sales Price Gross Living Area Total Rooms Total Bedrooms Total Bathrooms Location View Site Quality Age


Building Sketch

Borrower/Cli	ent Robert & Betty Marshall			
Property Add	ress 30393 Upper Bear Creek			
City	Evergreen	County Jefferson	State CO	Zip Code 80439
Lender	Bank Of The West			




Location Map

Borrower/Client	Robert & Betty Marshall							
Property Address	30393 Upper Bear Creek							
City	Evergreen	County	Jefferson	Stale	CO	Zip Code	80439	
Lender	Bank Of The West							



Flood Map

Borrower/Client	Robert & Betty Marshall			
Property Addres	s 30393 Upper Bear Creek			
City	Evergreen	County Jefferson	State CO	Zip Code 80439
Lender	Bank Of The West			



062713-TN1 File No. 201311438

UNIFORM APPRAISAL DATASET (UAD) DEFINITIONS ADDENDUM

(Source: Fannie Mae UAD Appendix D: UAD Field-Specific Standardization Requirements)

Condition Ratings and Definitions

C1

The improvements have been recently constructed and have not been previously occupied. The entire structure and all components are new and the dwelling features no physical depreciation.

Note: Newly constructed improvements that feature recycled or previously used materials and/or components can be considered new dwellings provided that the dwelling is placed on a 100 percent new foundation and the recycled materials and the recycled components have been rehabilitated/remanufactured into like-new condition. Improvements that have not been previously occupied are not considered "new" if they have any significant physical depreciation (that is, newly constructed dwellings that have been vacant for an extended period of time without adequate maintenance or upkeep).

00

The improvements feature no deferred maintenance, little or no physical depreciation, and require no repairs. Virtually all building components are new or have been recently repaired, refinished, or rehabilitated. All outdated components and finishes have been updated and/or replaced with components that meet current standards. Dwellings in this category are either almost new or have been recently completely renovated and are similar in condition to new construction.

Note: The improvements represent a relatively new property that is well maintained with no deferred maintenance and little or no physical depreciation, or an older property that has been recently completely renovated.

C3

The improvements are well maintained and feature limited physical depreciation due to normal wear and tear. Some components, but not every major building component, may be updated or recently rehabilitated. The structure has been well maintained.

Note: The improvement is in its first-cycle of replacing short-lived building components (appliances, floor coverings, HVAC, etc.) and is being well maintained. Its estimated effective age is less than its actual age. It also may reflect a property in which the majority of short-lived building components have been replaced but not to the level of a complete renovation.

C4

The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear. The dwelling has been adequately maintained and requires only minimal repairs to building components/mechanical systems and cosmetic repairs. All major building components have been adequately maintained and are functionally adequate.

Note: The estimated effective age may be close to or equal to its actual age. It reflects a property in which some of the short-lived building components have been replaced, and some short-lived building components are at or near the end of their physical life expectancy; however, they still function adequately. Most minor repairs have been addressed on an ongoing basis resulting in an adequately maintained property.

C5

The improvements feature obvious deferred maintenance and are in need of some significant repairs. Some building components need repairs, rehabilitation, or updating. The functional utility and overall livability is somewhat diminished due to condition, but the dwelling remains useable and functional as a residence.

Note: Some significant repairs are needed to the improvements due to the lack of adequate maintenance. It reflects a property in which many of its short-lived building components are at the end of or have exceeded their physical life expectancy but remain functional.

Ce

The improvements have substantial damage or deferred maintenance with deficiencies or defects that are severe enough to affect the safety, soundness, or structural integrity of the improvements. The improvements are in need of substantial repairs and rehabilitation, including many or most major components.

Note: Substantial repairs are needed to the improvements due to the lack of adequate maintenance or property damage. It reflects a property with conditions severe enough to affect the safety, soundness, or structural integrity of the improvements.

Quality Ratings and Definitions

Q1

Dwellings with this quality rating are usually unique structures that are individually designed by an architect for a specified user. Such residences typically are constructed from detailed architectural plans and specifications and feature an exceptionally high level of workmanship and exceptionally high-grade materials throughout the interior and exterior of the structure. The design features exceptionally high-quality exterior refinements and ornamentation, and exceptionally high-quality interior refinements. The workmanship, materials, and finishes throughout the dwelling are of exceptionally high quality.

Q2

Dwellings with this quality rating are often custom designed for construction on an individual property owner's site. However, dwellings in this quality grade are also found in high-quality tract developments featuring residence constructed from individual plans or from highly modified or upgraded plans. The design features detailed, high quality exterior ornamentation, high-quality interior refinements, and detail. The workmanship, materials, and finishes throughout the dwelling are generally of high or very high quality.

UNIFORM APPRAISAL DATASET (UAD) DEFINITIONS ADDENDUM

(Source: Fannie Mae UAD Appendix D: UAD Field-Specific Standardization Requirements)

Quality Ratings and Definitions (continued)

Q3

Dwellings with this quality rating are residences of higher quality built from individual or readily available designer plans in above-standard residential tract developments or on an individual property owner's site. The design includes significant exterior ornamentation and interiors that are well finished. The workmanship exceeds acceptable standards and many materials and finishes throughout the dwelling have been upgraded from "stock" standards.

04

Dwellings with this quality rating meet or exceed the requirements of applicable building codes, Standard or modified standard building plans are utilized and the design includes adequate fenestration and some exterior ornamentation and interior refinements. Materials, workmanship, finish, and equipment are of stock or builder grade and may feature some upgrades.

Q5

Dwellings with this quality rating feature economy of construction and basic functionality as main considerations. Such dwellings feature a plain design using readily available or basic floor plans featuring minimal fenestration and basic finishes with minimal exterior ornamentation and limited interior detail. These dwellings meet minimum building codes and are constructed with inexpensive, stock materials with limited refinements and ungrades.

റദ

Dwellings with this quality rating are of basic quality and lower cost; some may not be suitable for year-round occupancy. Such dwellings are often built with simple plans or without plans, often utilizing the lowest quality building materials. Such dwellings are often built or expanded by persons who are professionally unskilled or possess only minimal construction skills. Electrical, plumbing, and other mechanical systems and equipment may be minimal or non-existent. Older dwellings may feature one or more substandard or non-conforming additions to the original structure

Definitions of Not Updated, Updated, and Remodeled

Not Updated

Little or no updating or modernization. This description includes, but is not limited to, new homes.

Residential properties of fifteen years of age or less often reflect an original condition with no updating, if no major components have been replaced or updated. Those over fifteen years of age are also considered not updated if the appliances, fixtures, and finishes are predominantly dated. An area that is 'Not Updated' may still be well maintained and fully functional, and this rating does not necessarily imply deferred maintenance or physical/functional deterioration.

Updated

The area of the home has been modified to meet current market expectations. These modifications are limited in terms of both scope and cost.

An updated area of the home should have an improved look and feel, or functional utility. Changes that constitute updates include refurbishment and/or replacing components to meet existing market expectations. Updates do not include significant alterations to the existing structure.

Remodeled

Significant finish and/or structural changes have been made that increase utility and appeal through complete replacement and/or expansion.

A remodeled area reflects fundamental changes that include multiple alterations. These alterations may include some or all of the following: replacement of a major component (cabinet(s), bathtub, or bathroom tile), relocation of plumbing/gas fixtures/appliances, significant structural alterations (relocating walls, and/or the addition of) square footage). This would include a complete gutting and rebuild.

Explanation of Bathroom Count

Three-quarter baths are counted as a full bath in all cases. Quarter baths (baths that feature only a toilet) are not included in the bathroom count. The number of full and half baths is reported by separating the two values using a period, where the full bath count is represented to the left of the period and the half bath count is represented to the right of the period.

Example:

3.2 indicates three full baths and two half baths.

UNIFORM APPRAISAL DATASET (UAD) DEFINITIONS ADDENDUM (Source: Fannle Mae UAD Appendix D: UAD Field-Specific Standardization Requirements)

Abbreviations Used In Data Standardization Text

Abbreviatio	n Full Name	Fields Where This Abbreviation May Appear
ac	Acres	Area, Site
AdjPrk	Adjacent to Park	Location
AdjPwr	Adjacent to Power Lines	Location
A	Adverse	Location & View
ArmLth	Arms Length Sale	Sale or Financing Concessions
ba	Bathroom(s)	Basement & Finished Rooms Below Grade
br	Bedroom	Basement & Finished Rooms Below Grade
В	Beneficial	Location & View
Cash	Cash	Sale or Financing Concessions
CtySky	City View Skyline View	View
CtyStr	City Street View	View
Comm	Commercial Influence	Location
c	Contracted Date	Date of Sale/Time
Conv	Conventional	Sale or Financing Concessions
CrtOrd	Court Ordered Sale	Sale or Financing Concessions
DOM	Days On Market	Data Sources
е	Expiration Date	Date of Sale/Time
Estate	Estate Sale	Sale or Financing Concessions
FHA	Federal Housing Authority	Sale or Financing Concessions
GlfCse	Golf Course	Location
Glfvw	Golf Course View	View
Ind	Industrial	Location & View
in	Interior Only Stairs	Basement & Finished Rooms Below Grade
Lndfl	Landfill	Location
LtdSght	Limited Sight	View
Listing	Listing	Sale or Financing Concessions
Mtn	Mountain View	View
N	Neutral	Location & View
NonArm	Non-Arms Length Sale	Sale or Financing Concessions
BsyRd	Busy Road	Location
0	Other	Basement & Finished Rooms Below Grade
Prk	Park View	View
Pstrl	Pastoral View	View
PwrLn	Power Lines	View
PubTrn	Public Transportation	Location
rubiiii	Recreational (Rec) Room	Basement & Finished Rooms Below Grade
Relo	Relocation Sale	Sale or Financing Concessions
REO	REO Sale	Sale or Financing Concessions
Res	Residential	Location & View
RH	USDA - Rural Housing	Sale or Financing Concessions
	Settlement Date	Date of Sale/Time
s Short	Short Sale	Sale or Financing Concessions
sf	Square Feet	Area, Site, Basement
	Square Meters	Area, Site
sqm Unk	Unknown	Date of Sale/Time
VA	Veterans Administration	Sale or Financing Concessions
	Withdrawn Date	Date of Sale/Time
W	Withdrawn Date Walk Out Basement	Basement & Finished Rooms Below Grade
Wo		Basement & Finished Rooms Below Grade
WU	Walk Up Basement Water Frontage	Location Location
WtrFr		View
Wtr	Water View	View
Woods	Woods View	1 1/4/4

Other Appraiser-Defined Abbreviations

Abbreviation	Full Name	Fields Where This Abbreviation May Appear
	<u> </u>	

E & O Insurance

Borrower/Client	Robert & Betty Marshall						
Property Address	30393 Upper Bear Creek						
City	Evergreen	County	Jefferson	State CO	Zip Code	80439	
Lender	Bank Of The West						

, g, c.			<u></u>		
it usperte enc. (
		NAV	IGATORS INSUF	ANCE COMPAN	1
		THIS IS BOTH A C	LAIMS MADE AND	REPORTED INSURA	INCE POLICY:
a arri	this Pc	olicy applies to those (LAIMS THAT ARE FIR	ST MADE AGAINST THE	INSURED AND REPORTED IN
				RING THE POLICY PER	RAD,
				DLIGY CAREFULLY.	Vellande son and
	R	EAL ESTATE APPRA			SURANCE PULICI
			DECLARA		
		POLICY NUMBER: PHIZ	RALIZOSSUV REME	WAL OF:	and the state of t
power or the second	1.	NAMED INSUREO:	Troy Notzinger		
* 3	2,	ADDRESS:	30873 L. Suncreek Driv Evergreen, CO 80439	⁷ e	
;	3.	POLICY PERIOD: FROM 12:01 A.M. Standard Time a	; 07/20/2012 TO; t the address of the Nan	07/20/2013 ned Insured as stated in P	Jamber 2 above.
		(K.O.) Man changed that o	V (III)		
Balling Agency (1996)	4,	LIMITS OF LIABILITY: A. \$ 500,000 Da B. \$ 500,000 CI C. \$ 1,000,000 Da	ılm Expenses Limit of L mages Limit of Liebility	lability – Each Clalm - Policy Aggregate	
		D. \$1,000,000 Ch	ilm Expenses Limit of L	lability - Policy Aggragata	
	8.	DEDUCTIBLE (Inclusive of	ctalm expenses):	A. S. 500 ·	
	6.	PREMIUM: \$ 617.00			
. 5.0	7.	RETROACTIVE DATE:	07/20/2012		
	å.	FORMS ATTACHED:	NAV RAL MIC PF (02 NAV RAL 003 (02 11)	/(1) NAV RAL 300 CO (02 11)
		RAM ADMINISTRATOR:		: 410 Needham, MA 0240	
yan se tek t		eptance of this policy the Inserts bereto are the Inserted between the Inserted and the			tions and the Application and any policy ombodies of agreements his insurance.
	IM WITH	vess whereof, we have c	aused this policy to be	signed by our Prosiden	t and Secretary.
	-	Gnily Police	and the second s	stania Spanners J. J. J. J. J.	2. 0.
		St. 4 man. 1 . M. an. an. an.		tenj lidon Gal	
****	1	(Émily Miner) Secretary	Catherina alternation of f. " North Assessment	[Stanley A. Galans President	(ki)
					Zbavigatora
	NAV R	AL OEC (02.11)	Page 1 of 1		Insuring A World to Mottons

Appraisers License

Borrower/Client	Robert & Betty Marshall			
Property Address	30393 Upper Bear Creek			
City	Evergreen	County Jefferson	State CO	Zip Code 80439
Lender	Bank Of The West			

Depart	TATE OF COLOR tment of Regulatory Division of Real Es	/ Agencies	erredge e e e e e e e e e e e e e e e e e e
Active Licensed Appraiser 40031063		PRINTED ON SECURE	PAPER
Number	Jan 1 2012 Issue Date	Dec 31 2014 Expires	
TROY E NOFZINGER EVERGREEN, CO 80439		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
EVERGREEN, CO 80439	Sign of the state	7 . A	
get a second of the second of		s.	
PRANCIA WALL	eg 2 se ²		
Program Administr	rator	Licensee Signature	
**************************************	**************************************	; <u></u>	********
		*	
•			
		,	
		,	
		,	
		,	
		,	
		,	
		,	
		,	